

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Desmond Lee Kerr Wen

Date: 03 Dec 2024

Preliminary Advice

Insured Vehicle No	: SKW7681L	Accident Date	: 31/10/2024
TP Vehicle No	: SNM5767D	Assignment Date	: 08/11/2024
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 3
Date of Inspection	: 08/11/2024		
Inspection At	: MIRAI AUTO PERFORMANCE PTE LTD (HQ) 53 UBI AVE 1, #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,891.60
Revised Amount	:S\$	2,071.68
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,071.68
Lump Sum Repair	:S\$	1,650.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	170,000.00
COE / PARF Rebate	:S\$	129,040.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,960.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.