

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunus Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24110157/RVP3M4(N)**Date:** 03/01/2025REFERENCE

Insured/Claimant: TEO KOK KEONG Policy No: MPC24B00068101
Date of Loss: 26/10/2024 Nature of Claim: OD Claim No: DMPC2401503H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD8500H**
Make & Model: MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) Engine No: PE20789199
Reg. Date: 29/06/2016 (Man. Year: 2016) Chassis No: JM6GJ1072G0240090
Colour: Red Odometer: 140383 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$32,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,113.10	1,771.00	342.10	16.19
Miscellaneous Items	35.00	35.00	0.00	0.00
Labour	1,300.00	1,100.00	200.00	15.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,448.10	2,906.00	542.10	15.72
+ GST 9.00/9.00% (S\$)	310.33	261.54	48.79	15.72
Nett Amount (S\$)	3,758.43	3,167.54	590.89	15.72

INSPECTION

Date of Assignment: 06/11/2024 Present Location: Charn's Customcraft (HQ)
Date Inspected: 11/11/2024 Inspected At: CHARN'S CUSTOMCRAFT (HQ)
Estimated Period of Repair: 5.0 days BLOCK 1010 BUKIT MERAH LANE 3, #01-105
SINGAPORE 159724

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Jan 2025)
Parts:	143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD8500H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front logo (WCP)	Cut	36.00 F	*36.00 F
2	1		*Front logo base (WCP)	Cracked	65.00 F	*65.00 F
3	1		*Front bumper top garnish (WCP)	Deformed	185.00 F	*185.00 F
4	1		*Front bumper (WCP)	Cracked	550.00 F	*550.00 F
5	1		*Front bumper towing cover (WCP)	Missing	30.00 F	*30.00 F
6	1		*Front bumper RHS retainer (WCP)	Not Necessary	25.00 F	*- F
7	1		*Front bumper lower spoiler (NPA)	Not Necessary	-	-
8	1		*Front grille (WCP)	Cracked	135.00 F	*135.00 F
9	1		*Front grille moulding LHS (WCP) }	Cracked	140.00 F	*364.00 F
10	1		*Front grille moulding RHS (WCP) }	Cracked	140.00 F	-
11	1		*Front grille moulding (WCP) }	Cracked	370.00 F	-
<u>Supplementary #1</u>						
12	1		*Front bumper sponge (WCP)	Cracked	70.00 F	*70.00 F
13	1		*Lower cover (WCP)	Scratched	100.00 F	*100.00 F
14	1		*Reinforcement top garnish (WCP)	Scratched	75.00 F	*75.00 F

F=Franchise part.

Sub Total (\$\$)	1,921.00	1,610.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	192.10	161.00
Total Parts (\$\$)	2,113.10	1,771.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Front no.plate - S/NETT (Bent)	35.00	35.00
Sub Total (\$\$)			35.00	35.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Remove necessary parts; jacking, panel beating, repair and/or straighten front bonnet, front fenders LHS/RHS inclusive replacing the above.	New	600.00	500.00
2	Putty and respray front bonnet, front fenders LHS/RHS, front bumper and affected areas.	New	700.00	600.00
Gross Labour Cost (\$\$)			1,300.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >