

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24110158/AVP3E2

Date: 06/02/2025

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:			
Claimant Vehicle No :	SLC8004D	Insured Vehicle No :	SLA8342M		
Date of Loss:	05/11/2024	Nature of Claim:	TP	Claim No:	DMPC2401509H/02/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC8004D	Engine No:	PE20752207
Make & Model:	MAZDA 6, 2.0 (A)	Chassis No:	JM6GJ1072G0232636
Reg. Date:	26/05/2016 (Man. Year: 2016)	Odometer:	122157 km
Colour:	Black		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,483.68	4,701.52	2,782.16	37.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,010.00	690.00	40.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,183.68	5,711.52	3,472.16	37.81
Approved Total (Overridden) (\$\$)		4,550.00		
(\$\$)	9,183.68	4,550.00	4,633.68	50.46
+ GST 9.00/9.00% (\$\$)	826.53	409.50	417.03	50.46
Nett Amount (\$\$)	10,010.21	4,959.50	5,050.71	50.46

INSPECTION

Date of Assignment:	06/11/2024		
Date Inspected:	07/11/2024	Inspected At:	Modern Automotive Pte Ltd (HQ) Blk 3023A Ubi Road 1, #01-61 & #01-58 Singapore 408717
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2025)
Parts:	143	MAZDA 6 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC8004D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,211.90 FL	*1,211.90 FL
2	1		*FRONT BUMPER SIDE HOLDER - LH	Not Necessary	58.90 FL	*- FL
3	1		*FRONT BUMPER FOG LAMP COVER - LH	Not Necessary	65.10 FL	*- FL
4	1		*FRONT BUMPER FOG LAMP COVER CHROME MOULDING - LH	Not Necessary	70.20 FL	*- FL
5	1		*HEAD LAMP - LH	Cut	3,259.60 FL	*3,259.60 FL
6	1		*FRONT FENDER - LH	Dented	485.10 FL	*485.10 FL
7	1		*FRONT FENDER BRACKET - LH	Not Necessary	51.60 FL	*- FL
8	1		*FRONT FENDER INNER SHIELD - LH	Torn	195.30 FL	*195.30 FL
9	1		*FRONT LOWER ARM - LH	Not Necessary	579.60 FL	*- FL
10	1		*FRONT KNUCKLE ARM - LH	Not Necessary	502.70 FL	*- FL
11	1		*FRONT WHEEL HUB C/W BEARING - LH	Not Necessary	477.20 FL	*- FL
12	1		*FRONT SHOCK ABSORBER - LH	Not Necessary	471.90 FL	*- FL
13	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
14	1		*FRONT WHEEL RIM - LH	Cut	1,000.00 FS	*550.00 FS
15	1		*FRONT TYRE - LH	Not Necessary	250.00 FS	*- FS
16	1		*FRONT BUMPER FOG LAMP - LH	Not Necessary	325.50 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,034.60	5,731.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,550.92	1,030.38
Total Parts (\$\$)	7,483.68	4,701.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT FRONT LH PORTION & RENEW ABOVE PARTS	New	800.00	500.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	600.00	400.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO SPRAY TUFF COAT	New	100.00	0.00
5	TO PERFORM WHEEL ALIGNMENT	New	150.00	80.00
Gross Labour Cost (\$)			1,700.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >