

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110163/KQP3E2**Date:** 12/11/2024REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No :

SNM3267T

Insured Vehicle No :

YN9713Y

Date of Loss: 04/10/2024

Nature of Claim:

TP

Claim No:

DMCF2400080H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNM3267T**Make & Model: MERCEDES-BENZ EQB250, ELECTRIC ART PA
BSP AHBA (A)

Engine No: HIDDEN

Reg. Date: 14/09/2023 (Man. Year: 2022)

Chassis No: W1N2436012N015058

Colour: Metallic Red

Odometer: 29289 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R19

Rear Tyre Size: 235/50 R19

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,829.40	4,408.20	421.20	8.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	1,150.00	1,460.00	55.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	7,439.40	5,558.20	1,881.20	25.29
+ GST 9.00/9.00% (\$\$)	669.55	500.24	169.31	25.29
Nett Amount (\$\$)	8,108.95	6,058.44	2,050.51	25.29

INSPECTION

Date of Assignment: 07/11/2024

Date Inspected:

15/10/2024

Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair:

4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Nov 2024)
Parts:	M1-SUV	MERCEDES-BENZ EQB250 ELECTRIC ART PA BSP AHBA (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNM3267T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY - LH	Cut	1,738.00 FN	*1,738.00 FN
2	1		*FRONT FENDER - LH	Buckled	1,007.00 FN	*1,007.00 FN
3	1		*FRONT FENDER WHEEL ARCH GARNISH - LH	Cut	272.00 FN	*272.00 FN
4	1		*FRONT FENDER INNER SHIELD - LH (FRONT)	Serviceable	228.00 FN	*- FN
5	1		*FRONT FENDER INNER SHIELD - LH (REAR)	Serviceable	240.00 FN	*- FN
6	1		*FRONT BUMPER	Buckled / Cracked	1,650.00 FN	*1,650.00 FN
7	1		*FRONT BUMPER SIDE RETAINER - LH	Necessary	24.00 FN	*24.00 FN
8	6		*FRONT BUMPER SENSOR SEALS	Necessary	72.00 FN	*72.00 FN
9	15		*FRONT BUMPER CLIPS	Necessary	135.00 FN	*135.00 FN

F=Franchise part. N=NettItemDisc.

Sub Total (\$\$)	5,366.00	4,898.00
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	536.60	489.80
Total Parts (\$\$)	4,829.40	4,408.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT BUMPER SENSOR	New	100.00	60.00
2	TO CHECK & RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT & STRAIGHTEN LH FRONT FENDER INNER PANEL, LH FRONT CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, REFIT & ADJUST THE SAME	New	1,000.00	400.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,000.00	440.00
5	TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PANELS	New	80.00	30.00
6	TO RESET & REPROGRAM HEADLAMP FAULT CODE	New	350.00	200.00
Gross Labour Cost (S\$)			2,610.00	1,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >