



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL :

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : YN9713Y

CLAIM TYPE : THIRD PARTY

TP INS. CO. : ECICS LIMITED

ACCIDENT DATE : 04/10/2024

TP VEH REG NO : YN9713Y

ESTIMATE

NO : QUOT202410-000034(00)

DATE : 14/10/2024

POLICY NO : SP2003907937

VEH REG NO : SNM3267T

MAKE/MODEL : MERCEDES BENZ EQB250

CHASSIS NO : W1N2436012N015058

ENGINE NO :

REG. DATE : 2022

Not Withheld

Running B4 pain

15/10/24 4 days

\$5558.20

Estimate Repair Cost to Vehicle No : SNM3267T

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Headlamp assy - LH	1	1,738.00	1,738.00
2 Front fender - LH	1	1,007.00	1,007.00
3 Front fender wheel arch garnish - LH	1	272.00	272.00
4 Front fender inner shield - LH (front)	1	228.00	228.00
5 Front fender inner shield - LH (rear)	1	240.00	240.00
6 Front bumper	1	1,650.00	1,650.00
7 Front bumper side retainer - LH	1	24.00	24.00
8 Front bumper sensor seals	6	12.00	72.00
9 Front bumper clips	15	9.00	135.00
			5,366.00
		Less 10%	536.60
			4,829.40
LABOUR			
10 To remove & refit front bumper sensor	1	100.00	100.00
11 To check & rectify wiring system	1	80.00	80.00
12 To panel beat & straighten LH front fender inner panel, LH front chassis frame, including replacement of parts and align where necessary, refit & adjust the same	1	1,000.00	1,000.00
13 To putty and spray paint on affected areas	1	1,000.00	1,000.00
14 To apply rust-proofing on repaired and replaced panels	1	80.00	80.00
15 To reset & reprogram headlamp fault code	1	350.00	350.00
			2,610.00

TOTAL S\$ 7,439.40

ADD GST @ 9.00% 669.55

GRAND TOTAL S\$ 8,108.95

SINGAPORE DOLLAR EIGHT THOUSAND ONE HUNDRED EIGHT AND CENTS NINETY-FIVE ONLY

Net: \$4,408.20

Labour: \$1,200.00

\$5,608.20

9% \$504.74

\$6,112.94

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

FOR TONG LUCK AUTO PTE LTD