



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2505398

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 14/08/2025
Reference CD/LPC24110165/Apa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMS 362B
Insured Veh. GBH 3472K
Claim No. 24/24/24/VC05/030138
Policy No. Z24VC05023073
Accident Date 04/11/2024
Inspection Date 22/04/2025

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CD/LPC24110165/Apa3q2(N)	
			Date: 14/08/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 3472K	Veh. Inspected	SMS 362B
	Policy No.	Z24VC05023073	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030138	Excess (\$)	0.00
	Assign From	CHARMAINE KONG	Assign Date	22/04/2025
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	GK82103480	Colour	RED
	Odometer	174519 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	TOURADOR	6 mm
	L/H Front Tyre	185/60 R15	TOURADOR	6 mm
	R/H Rear Tyre	185/60 R15	TOURADOR	6 mm
	L/H Rear Tyre	185/60 R15	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/11/2024	Inspection Date	22/04/2025
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 362B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,189.00	1,189.00
2	REAR BUMPER SIDE HOLDER @ \$61.35	N/S CRACKED	122.70	61.35
1	REAR BUMPER CLIPS	NECESSARY	60.00	50.00
1	REAR LH LAMP	CRACKED	494.00	494.00
1	REAR LH FENDER	DISTORTED	1,010.90	1,010.90
1	REAR LH FENDER INNER SHIELD	TORN	105.80	105.80
1	REAR LH SPORT RIM	NOT NECESSARY	800.00	-
1	REAR LH TYRE	NOT NECESSARY	380.00	-
1	REAR LH QUATER GLASS RUBBER	NECESSARY	210.30	210.30
1	REAR FENDER END SEAL	TORN	165.50	165.50
	LESS 20% DISCOUNT		-907.64	-657.37
			3,630.56	2,629.48
	<u>LABOUR</u>			
	TO SUPPLY REAR QUATER GLASS SEALANT.		80.00	50.00
	REMOVE AND REINSTALL QUATER GLASS.		100.00	60.00
	REMOVE AND REINSTALL PETROL TANK.		150.00	80.00
	REMOVE AND REINSTALL REVERSE SENSOR.		100.00	50.00
	REMOVE AND REINSTALL ROOF LINING.	NOT NECESSARY	150.00	-
	REMOVE, REPLACE AND REPAIR CONSISTENT TO THE ACCIDENT.		1,000.00	600.00
	RESPRAY PAINTING.		1,000.00	400.00
	TUFF KOTE.		100.00	80.00
	REMOVE AND REFIX BODY STICKER.		1,000.00	800.00
			3,680.00	2,120.00
	GRAND TOTAL		7,310.56	4,749.48

Report Ref No. CD/LPC24110165/Apa3q2(N)



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,800.00
---	--	--	-----------------

Report Ref No. CD/LPC24110165/Apa3q2(N)

Market Value: \$71,000.00(est) less LTA Rebate: \$22,776.00(est) = Nett Value :\$48,224.00(est)

ADRIAN LING WAI PING


B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser





DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMS 362B



PHOTOGRAPHS FOR VEHICLE NO. : SMS 362B






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 5)

PHOTOGRAPHS FOR VEHICLE NO. : SMS 362B





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 5)

PHOTOGRAPHS FOR VEHICLE NO. : SMS 362B



PHOTOGRAPHS FOR VEHICLE NO. : SMS 362B



PHOTOGRAPHS FOR VEHICLE NO. : SMS 362B



PHOTOGRAPHS FOR VEHICLE NO. : SMS 362B



PHOTOGRAPHS FOR VEHICLE NO. : SMS 362B



PHOTOGRAPHS FOR VEHICLE NO. : SMS 362B



PHOTOGRAPHS FOR VEHICLE NO. : SMS 362B

