

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CS/AIG24110168/ENP3E2
Date: 03/03/2025**REFERENCE**

Insured/Claimant:	CDL MANAGEMENT SERVICES PTE LTD	Policy No:	7230058635
Date of Loss:	06/11/2024	Nature of Claim:	OD Claim No: 7131753422SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBK888Z	Engine No:	HIDDEN
Make & Model:	AUDI E-TRON, 50 QUATTRO (A)	Chassis No:	WAUZZZGE6PB000230
Reg. Date:	19/06/2023 (Man. Year: 2022)	Odometer:	12027 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$255,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,679.00	26,597.04	22,081.96	45.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,752.00	10,252.00	5,500.00	34.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	64,431.00	36,849.04	27,581.96	42.81
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	63,831.00	36,249.04	27,581.96	43.21
+ GST 9.00/9.00% (\$\$)	5,744.79	3,262.41	2,482.38	43.21
Nett Amount (\$\$)	69,575.79	39,511.45	30,064.34	43.21

INSPECTION

Date of Assignment:	08/11/2024		
Date Inspected:	12/11/2024	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	9.0 days		

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Repair	3,254.00 FS	*- FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	696.00 FS	*- FS
3	1	*FRONT BUMPER CLOSING ELEMENTS - CENTER	Broken	279.00 FS	*223.20 FS
4	1	*FRONT BUMPER FOAM - LH INNER	Not Necessary	38.00 FS	*- FS
5	2	*FRONT BUMPER LOWER GRILLE COVER - LH / RH	Not Necessary	88.00 FS	*- FS
6	1	*FRONT BUMPER FOAM - SQUARE	Not Necessary	169.00 FS	*- FS
7	1	*FRONT BUMPER FOAM - LONG	Not Necessary	141.00 FS	*- FS
8	1	*FRONT PLASTIC FOAM STRIP - LOWER COVER	Not Necessary	151.00 FS	*- FS
9	1	*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	318.00 FS	*- FS
10	1	*FRONT BUMPER GRILLE - CENTER	Not Necessary	192.00 FS	*- FS
11	1	*FRONT BUMPER CLOSING ELEMENT - LOWER	Not Necessary	263.00 FS	*- FS
12	2	*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	228.00 FS	*- FS
13	1	*FRONT BUMPER IMPACT PROTECTION - LOWER	Not Necessary	1,011.00 FS	*- FS
14	2	*FRONT BUMPER SPOILER - LH / RH	Not Necessary	248.00 FS	*- FS
15	2	*FRONT BUMPER AIR GUIDE - LH / RH INNER	Not Necessary	136.00 FS	*- FS
16	2	*FRONT BUMPER AIR GUIDE - LH / RH OUTER	Not Necessary	106.00 FS	*- FS
17	2	*FRONT BUMPER TRIM - LH / RH	Not Necessary	146.00 FS	*- FS
18	2	*FRONT BUMPER AIR GUIDE - LH / RH BRILLIANT BLACK	Not Necessary	300.00 FS	*- FS
19	1	*RADIATOR GRILLE	Cut	2,582.00 FS	*2,065.60 FS
20	1	*RADIATOR GRILLE AUDI EMBLEM COVER	Not Necessary	83.00 FS	*- FS
21	1	*RADIATOR GRILLE STRIKER PLATE	Broken	275.00 FS	*219.60 FS
22	2	*RADIATOR GRILLE COVER - LH / RH	Not Necessary	136.00 FS	*- FS
23	1	*FRONT 360 DEGREE CAMERA	Not Necessary	1,253.00 FS	*- FS
24	1	*FRONT 360 DEGREE CAMERA COVER CAP	Not Necessary	158.00 FS	*- FS
25	1	*FRONT 360 DEGREE CAMERA BRACKET	Not Necessary	116.00 FS	*- FS
26	1	*FRONT 360 DEGREE CAMERA SECURING PLATE	Not Necessary	104.00 FS	*- FS
27	1	*FRONT BUMPER TOP COVER	Broken	134.00 FS	*106.80 FS
28	1	*NOTICE	Necessary	25.00 FS	*19.68 FS
29	1	*FRONT BUMPER TOP COVER	Broken	133.00 FS	*106.00 FS
30	1	*FRONT BUMPER TOP BRACKET	Broken	540.00 FS	*431.60 FS
31	1	*FRONT REINFORCEMENT BEAM	Not Necessary	1,663.00 FS	*- FS
32	1	*FRONT CROSS MEMBER	Not Necessary	521.00 FS	*- FS
33	2	*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	144.00 FS	*- FS
34	2	*LED HEADLIGHT, MATRIX EMBLEM - LH / RH	N/S Cut / O/S Broken	19,674.00 FS	*15,739.20 FS
35	2	*LIFT CYLINDER - LH / RH	Not Necessary	566.00 FS	*- FS
36	1	*LIFT CYLINDER HOSE	Not Necessary	122.00 FS	*- FS
37	1	*BONNET	Not Necessary	233.00 FS	*- FS
38	2	*BONNET HINGE - LH / RH	Not Necessary	420.00 FS	*- FS
39	2	*BONNET IMPACT PROTECTION - LH / RH	Necessary	112.00 FS	*88.16 FS
40	1	*BONNET IMPACT PROTECTION - CENTER	Necessary	38.00 FS	*30.40 FS
41	1	*PLENUM CHAMBER COVER	Not Necessary	249.00 FS	*- FS
42	2	*BONNET STRIKER - LH / RH	Not Necessary	298.00 FS	*- FS
43	1	*BONNET RELEASE ELEMENT	Not Necessary	73.00 FS	*- FS
44	2	*BONNET LOCK - LH / RH	Bent	491.00 FS	*392.80 FS
45	1	*BONNET BOWDEN CABLE - CENTER	Not Necessary	71.00 FS	*- FS
46	1	*BONNET BOWDEN CABLE - CABLE	Not Necessary	12.00 FS	*- FS
47	1	*BONNET CABLE	Not Necessary	92.00 FS	*- FS
48	2	*FRONTAL TOP COVER - LH / RH	Not Necessary	254.00 FS	*- FS
49	2	*FRONTAL TOP COVER - LH / RH	Not Necessary	124.00 FS	*- FS
50	2	*RADIATOR AIR GUIDE - LH / RH	Not Necessary	84.00 FS	*- FS
51	2	*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	53.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
52	1	*RADIATOR LOURVE - LOWER	Not Necessary	272.00 FS	*- FS
53	1	*RADIATOR LOURVE SERVOMOTOR	Not Necessary	209.00 FS	*- FS
54	2	*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	188.00 FS	*- FS
55	2	*FRONT WHEEL ARCH COVER - LH / RH	Necessary	728.00 FS	*581.60 FS
56	1	*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
57	1	*SUNDRIES	Necessary	500.00 FS	*33.28 FS
58	1	*BONNET (SUPPLEMENTARY)	Dented	5,890.00 FS	*4,712.00 FS
59	1	*FRONT LOCK CARRIER (SUPPLEMENTARY)	Broken	1,443.00 FS	*1,154.40 FS
60	1	*FRONT FENDER UPPER BRACKET RHS (SUPPLEMENTARY)	Bent	105.00 FS	*83.60 FS
61	1	*FRONT FENDER UPPER BRACKET LHS (SUPPLEMENTARY)	Bent	111.00 FS	*88.40 FS
62	10	*READY MIX-COOLANT 1L (SUPPLEMENTARY)	Necessary	553.00 FS	*442.40 FS
63	1	*STICKER FOR AIRCON (SUPPLEMENTARY)	Necessary	23.00 FS	*18.32 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	48,679.00	26,597.04
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	900.00	900.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO REPAIR BOTH FRONT FENDERS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,600.00	1,200.00
4	TO RESPRAY FRONT BUMPER, BONNET AND BOTH FRONT FENDERS	New	4,400.00	1,300.00
5	TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM WITH VAS TOOLS	New	800.00	800.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
7	TO DE-ENERGEISING HIGH VOLTAGE SYSTEM. DEACTIVATION AND ACTIVATION (SUPPLEMENTARY)	New	480.00	480.00
8	TO REMOVE AND REINSTALL AIRCON CONDENSER AND RADIATOR. TO CHECK ON ELECTRICAL FANS AND CONTROL UNIT (SUPPLEMENTARY)	New	1,800.00	1,800.00
9	TO CARRY OUT VACUUM AND REGAS FOR R1234 (SUPPLEMENTARY)	New	1,200.00	1,200.00
10	TO REMOVE AND RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION (SUPPLEMENTARY)	New	1,800.00	1,800.00
Gross Labour Cost (\$\$)			15,752.00	10,252.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >