


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 06.11.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKP288Y**
MODEL : **BMW 420I**
DATE OF ACCIDENT : 05.11.2024
TIME OF ACCIDENT : 17:00 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Delud</i>	1	\$ 1,594.55	\$ 1,594.55
2	FRONT BUMPER LOGO <i>new</i>	1	\$ 68.50	\$ 68.50
3	FRONT BUMPER SIDE BOTTOM COVER GARNISH RH <i>new</i>	1	\$ 276.65	\$ 276.65
4	FRONT BUMPER SIDE GRILLE RH <i>cut</i>	1	\$ 168.50	\$ 168.50
5	FRONT BUMPER SIDE GRILLE INNER GARNISH RH <i>new</i>	1	\$ 128.30	\$ 128.30
6	FRONT BUMPER SPONGE <i>cut</i>	1	\$ 258.30	\$ 258.30
7	FRONT BUMPER LOWER BEAM <i>new</i>	1	\$ 197.35	\$ 197.35
8	FRONT BUMPER FOGLAMP (LED) RH <i>cut</i>	1	\$ 735.20	\$ 735.20
9	FRONT BUMPER FOGLAMP COVER GARNISH RH <i>cut</i>	1	\$ 145.60	\$ 145.60
10	FRONT BUMPER SENSOR <i>2nd 1 piece</i>	2	\$ 332.00	\$ 664.00
11	ENGINE UNDERCOVER <i>new</i>	1	\$ 68.50	\$ 68.50
12	HEADLAMP RH <i>cut</i>	1	\$ 3,329.45	\$ 3,329.45
13	HEADLAMP TOP RUBBER RH <i>new</i>	1	\$ 28.40	\$ 28.40
14	HEADLAMP LOWER BRACKET RH <i>new</i>	2	\$ 114.80	\$ 229.60
15	HEADLAMP LOWER GARNISH RH <i>new</i>	1	\$ 118.55	\$ 118.55
16	HEADLAMP TOP COVER GARNISH RH <i>new</i>	1	\$ 296.70	\$ 296.70
17	FRONT FENDER INNER COWLING RH <i>new</i>	1	\$ 366.90	\$ 366.90

TOTAL PRICE \$ 8,675.05
LESS 5% \$ 433.75
SUB TOTAL PRICE \$ 8,241.30

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>na</i>	1	\$ 50.00	\$ 50.00

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SKP288Y**
MODEL : **BMW 420I**
DATE OF ACCIDENT : 05.11.2024
TIME OF ACCIDENT : 17:00 HOURS

2	FRONT BUMPER SIDE BOTTOM COVER GARNISH RH CLIP (SET)	1	\$ 30.00	\$ 30.00
3	ENGINE UNDERCOVER CLIP (SET)	1	\$ 50.00	\$ 50.00
4	FRONT FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00

TOTAL \$ 180.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	250
3	TUFF COAT	\$ 250.00	X
4	WIRING CHECK	\$ 250.00	30
5	REFOCUS HEADLAMP BEAM	\$ 80.00	X
6	REMOVE AND REFIX FRONT SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 850.00	120

TOTAL \$3,510.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 8,421.30
TOTAL LABOUR COST : \$ 3,510.00
TOTAL REPAIR COST : \$ 11,931.30

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 6984.17
L/S: S.61e ✓