6/18/25, 9:40 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24110174/KMA3Q2

PE20795877

Date: 18/06/2025

Engine No:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7230099269 **Claimant Vehicle** SNQ7069B Insured Vehicle No: SNM6926E

No:

Date of Loss: 05/11/2024 Nature of Claim: TP Claim No: 1056840261SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SNQ7069B Reg No:

MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT Make & Model:

Reg. Date: 28/07/2016 (Man. Year: 2016) Chassis No: JM6GJ1072G0242242

Metallic Dark Blue Colour: Odometer: 125150 km

Engine Capacity: 1998 cc Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 225/55 R17 Rear Tyre Size: Front Left Side: Rear Left Side: Michelin 3 mm Michelin 5 mm Rear Right Side: Front Right Side: Michelin 5 mm Michelin 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,690.92	5,418.72	1,272.20	19.01
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,070.00	920.00	1,150.00	55.56
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,760.92	6,338.72	2,422.20	27.65
	Approved Total (Overridden) (S\$)		5,050.00		
	Nett Amount (S\$)	8,760.92	5,050.00	3,710.92	42.36
	Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 07/11/2024

Guan Motor Works (HQ)

176 Sin Ming Drive #02-03 Sin Ming Autocare Date Inspected: 07/11/2024 Inspected At:

Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,211.90 FL	*1,211.90 FL
2	1		*FRONT BUMPER RH CHROME GRILLE	Cut	144.60 FL	*144.60 FL
3	1		*FRONT BUMPER RH FOG LAMP COVER	Serviceable	144.60 FL	*- FL
4	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	22.70 FL	*22.70 FL
5	1		*FRONT BUMPER INNER FOAM	Serviceable	77.10 FL	*- FL
6	1		*FRONT BUMPER INNER REINFORCEMENT	Bent	579.60 FL	*579.60 FL
7	1		*RH HEADLAMP	Cut	4,057.00 FL	*4,057.00 FL
8	1		*FRONT GRILLE	Mtg Cracked	202.60 FL	*202.60 FL
9	1		*FRONT GRILLE CENTRE MAZDA LOGO	Necessary	55.50 FL	*55.50 FL
10	1		*FRONT GRILLE LOWER CHROME FINISH	Cut	79.00 FL	*79.00 FL
11	1		*FRONT RH FENDER	Repair	383.70 FL	*- FL
12	1		*FRONT TOP PANEL	Mtg Cracked	420.50 FL	*420.50 FL
13	1		*BTL RADIATOR COOLANT	Not Necessary	50.00 FS	*- FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	_		
				Sub Total (S\$)	7,428.80	6,773.40
			- List Item Discount on L Items	10.00/20.00% (S\$)	737.88	1,354.68
				Total Parts (S\$)	6,690.92	5,418.72
			Report was unsubmitted during this			

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING /WELDING AND REPLACEMENT OF DAMAGES	New	800.00	300.00
2	TO PUTTY AND SPRAY SPRAY PAINTING CHARGES	New	1,000.00	600.00
3	TO CHECK WIRINGS AND LIGHTINGS	New	40.00	20.00
4	TO REMOVE,REFIT AIR CON CONDENSER ,AIR CON PIPINGS /HOSES,INCLUDING VACUUN & REFILL OF AIR CON GAS	New	150.00	0.00
5	TO SUPPLY AND APPLY ANTI RUST TREATMENT	New	80.00	0.00
	Gross Labou	ır Cost (S\$)	2,070.00	920.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >