

ASS. REC. BY:

REF:

A/G/ 24/10/24/kma3

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/11 21/24 @ 5050/ Centur

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No. 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SNQ7069B

No.	Qty	List Items	
1	1	Front bumper	\$ CM 1,211.90 ✓
2	1	Front bumper RH chrome-finish <i>Grille</i>	\$ G 144.60 ✓
3	1	Front bumper RH fog lamp cover	\$ S 144.60 X
4	1	Front bumper RH side retainer	\$ D 22.70 ✓
5	1	Front bumper inner foam	\$ R 77.10 X
6	1	Front bumper inner reinforcement	\$ R 579.60 ✓
7	1	RH headlamp	\$ G 2,369.80 ✓ 4057.00
8	1	Front grille	my \$ CM 202.60 ✓
9	1	Front grille centre "MAZDA" logo	\$ R 55.50 ✓
10	1	Front grille lower chrome finish	\$ G 79.00 ✓
11	1	Front RH fender	\$ R 383.70 X
12	1	Front top panel	my \$ CM 420.50 X
			20% \$ 6,691.60
			Less 10% \$ 669.16
			Total : \$ 6,022.44

Special Nett Items

13	1 Btl Radiator coolant	\$ NN 50.00 X
----	------------------------	---------------

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.	\$ 800.00 30d
2	To putty and spray Spray Paintings charges.	\$ 1,000.00 60d
3	To check wirings and lightings.	\$ 40.00 2d
4	To remove, refit air con condenser, air con pipings/hoses, including vacuum & refill of air con gas.	\$ NN 150.00 X
5	To supply and apply anti rust treatment	\$ NN 80.00 X
		Total : \$ 2,070.00

Total Parts and Labour : \$ 8,142.44

*Not Withheld
1/100 & 5050h
Presurvey After Paint
4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

07.11.2024

AMENDMENT ESTIMATE FOR Mazda 6 - SNO 7069 B

	<u>List Items</u>	
1 pc.	RH headlamp	\$ 4,057.00