

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24110181/KMA3Q2**Date:** 29/01/2026**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 7220080968  
**Claimant Vehicle No :** SLQ531C **Insured Vehicle No :** GBK4873P  
 Date of Loss: 08/11/2024 Nature of Claim: TP Claim No: 9681007463SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLQ531C**  
 Make & Model: TOYOTA COROLLA AXIO, 1.5 G (A) Engine No: 2NR8701194  
 Reg. Date: 27/06/2017 (Man. Year: 2016) Chassis No: NRE1610023604  
 Colour: Metallic Pearl White Odometer: 251936 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

**CONDITION OF TYRES**

Front Tyre Size: 251936 Rear Tyre Size: 251936  
 Front Left Side: Michelin 8 mm Rear Left Side: Michelin 4 mm  
 Front Right Side: Michelin 8 mm Rear Right Side: Michelin 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,355.60	3,872.07	483.53	11.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,360.00	300.00	18.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,015.60</b>	<b>5,232.07</b>	<b>783.53</b>	<b>13.02</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,150.00</b>		
<b>(S\$)</b>	6,015.60	4,150.00	1,865.60	31.01
<b>+ GST 9.00/9.00% (S\$)</b>	541.40	373.50	167.90	31.01
<b>Nett Amount (S\$)</b>	<b>6,557.00</b>	<b>4,523.50</b>	<b>2,033.50</b>	<b>31.01</b>
<b>+ Loss of Use (6.0 x S\$80.00/day) (S\$)</b>		480.00		
<b>+ Doc/Search Fee (S\$)</b>		2.18		
<b>Nett Liability (S\$)</b>		<b>5,005.68</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,000.00</b>		

**INSPECTION**

Date of Assignment: 14/11/2024  
 Date Inspected: 14/11/2024 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)  
 Blk 1019 #01-374/382, Yishun Industrial Park A  
 Singapore 768761  
 Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** Daphne Lee Mooi Ngiuk

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	774.30 FL	*774.30 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	153.50 FL	*153.50 FL
3	1		*REAR BUMPER LH BRACKET	Repair	92.10 FL	*- FL
4	6		*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
5	1		*TAILLAMP LH	Cracked	876.60 FL	*876.60 FL
6	1		*TAILLAMP LOWER BRACKET LH	Repair	99.80 FL	*- FL
7	1		*REAR BOOT	Buckled	1,299.10 FL	*1,299.10 FL
8	1		*REAR BOOT LOGO	Necessary	68.80 FL	*68.80 FL
9	1		*REAR BOOT EMBLEM (AXIO)	Necessary	63.20 FL	*63.20 FL
10	1		*REAR BOOT INNER LOCK	Repair	183.40 FL	*- FL
11	1		*REAR BOOT INNER RUBBER	Serviceable	269.40 FL	*- FL
12	1		*REAR BOOT EMBLEM (G)	Necessary	59.10 FL	*59.10 FL
13	1		*REAR BOOT OUTER MOULDING	Dented	301.30 FL	*301.30 FL
14	1		*REAR PANEL	Bent	902.30 FL	*902.30 FL
15	1		*REAR PANEL INNER TOP GARNISH	Mtg Cracked	374.50 FL	*374.50 FL
16	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,740.80</b>	<b>5,096.10</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,385.20	1,224.03
<b>Total Parts (\$\$)</b>	<b>4,355.60</b>	<b>3,872.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REAR BUMPER ASSY BOOT & ATTACHMENT TO CUT ,WELD & RENEW REAR PANEL KNOCK & REPAIR REAR LH FENDER AND REALIGN THE SAME	New	800.00	600.00
2	PUTTY & RESPRAY ON REAR BUMPER ,BOOT ,REAR LH FENDER ,REAR PANEL AND REAR AFFECTED AREAS	New	800.00	700.00
3	RUSTPROOFING	New	30.00	30.00
4	REMOVE & REFIX REAR REVERSE CAMERA ,REAR REVERSE SENSOR	New	30.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,660.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >