3/27/25, 2:23 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110183/DUA3Q2

Date: 27/03/2025

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549\_05

**Claimant Vehicle GBG8228Y** Insured Vehicle No: GBH8184J

No:

Date of Loss: 07/11/2024 Nature of Claim: TP Claim No: MFL2024D0013247

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **GBG8228Y** 

Make & Model: NISSAN NV200, 1.6 DX-2 (A) Engine No: HR16083848D Reg. Date: 16/06/2017 (Man. Year: 2016) VM20103672 Chassis No: Colour: Odometer: 119198 km Black

**Engine Capacity:** 1597 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

175/40 R14 175/40 R14 Front Tyre Size: Rear Tyre Size: Front Left Side: Continental 5 mm Rear Left Side: Continental 5 mm Front Right Side: Continental 5 mm Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,754.00	4,115.21	6,638.79	61.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,720.00	1,190.00	1,530.00	56.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,474.00	5,305.21	8,168.79	60.63
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	13,474.00	4,200.00	9,274.00	68.83
+ Loss of Use (7.0 x S	\$65.00/day) (S\$)	455.00		
+ Doc/	Search Fee (S\$)	27.25		
N	ett Liability (S\$)	4,682.25		
Global Sum	Settlement (S\$)	4,650.00		

**INSPECTION** 

Date of Assignment: 13/11/2024

Alfred Auto Services & Supplies (HQ)

Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio 13/11/2024 Inspected At: Date Inspected:

Industrial Park 2

Singapore 569538

Estimated Period of Repair: 5.0 days

Adjuster: **BRYAN TANI** Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 31 Dec 2024)

Parts: N/A NISSAN NV200 1.6 DX-2 (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBG8228Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	2,499.60 F	*1,978.40 FL
2	2		*REAR BOOT ABSORBER	Not Necessary	656.00 F	*- FL
3	1		*REAR BOOT HANDLE GARNISH	Mtg Broken	454.00 F	*235.50 FL
4	1		*REAR BOOT LOCK	Damaged	391.00 F	*391.00 FL
5	1		*REAR BOOT LOCK CATCH	Repair	245.00 F	*- FL
6	2		*REAR BOOT NO PLATE LAMP	Not Necessary	190.00 F	*- FL
7	1		*REAR BOOT HANDLE OPENER	Deformed	199.00 F	*48.60 FL
8	1		*REAR WINDSCREEN INNER SEAL	Necessary	90.00 FS	*30.00 FS
9	1		*SET REAR WINDSCREEN REPAIR KIT & SEALANT	Necessary	180.00 FS	*40.00 FS
10	1		*REAR BOOT WEATHERSTRIP	Deformed	499.80 F	*128.00 FL
11	1		*REAR BOOT INNER BOARD	Not Necessary	599.80 F	*- FL
12	12		*REAR BOOT CLIPS	Not Necessary	60.00 F	*- FL
13	1		*REAR BOOT 70KM/H STICKER	Necessary	20.00 FS	*20.00 FS
14	1		*REAR BOOT 5 PAX STICKER	Necessary	20.00 FS	*20.00 FS
15	2		*REAR LAMP	Not Necessary	820.00 F	*- FL
16	1		*REAR BUMPER	Deformed	830.00 F	*698.20 FL
17	2		*REAR BUMPER SIDE RETAINER	Not Necessary	396.00 F	*- FL
18	4		*REAR BUMPER CLIPS	Necessary	24.00 FS	*15.00 FS
19	1		*SET REAR PARKING SENSOR	Damaged	490.00 FS	*150.00 FS
20	1		*REAR SPARE TYRE HOLDER ASSY	Not Necessary	598.00 F	*- FL
21	1		*REAR BUMPER SPONGE	Torn	699.00 F	*185.00 FL
22	1		*REAR END PANEL	Buckled	792.80 F	*602.20 FL
F=Fra	ınchise	part. S=SpcN	Nett. L=ListItemDisc.	_		
				Sub Total (S\$)	10,754.00	4,541.90
			- List Item Discount on L Items	0.00/10.00% (S\$)	0.00	426.69
				Total Parts (S\$)	10,754.00	4,115.21

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	<u>our Items</u>			
1	TO CHECK WIRING ,REMOVE & REFIT INNER WIRE	New	120.00	40.00
2	TO REMOVE & REFIT REAR WINDSCREEN	New	180.00	120.00
3	TO KNOCKING STRAIGHTENING ,REPAIR & RENEW ALL ACCIDENT DAMAGED AREA	New	1,100.00	600.00
4	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA	New	1,200.00	400.00
5	TO RUST PROOF ALL ACCIDENT AFFECTED AREA	New	120.00	30.00
	Gross Labour Cost (S\$)		2,720.00	1,190.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >