

Accord Auto Services Pte Ltd (Co.Reg.No.201113141K)

10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point

Singapore 568047

Tel: 64819517/85715140 Fax: 64819515 Email: admin@mycarworkshop.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPU24B00022900	Date of Loss:	29/10/2024
Vehicle Reg. No.:	SNL4789C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MUHAMMED FAIROL BIN ABDULLAH		

Make/Model:	TOYOTA NOAH HYBRID, 1.8 (A)	Vehicle Reg. Date:	15/08/2023
Vehicle Colour:	WHITE		
Engine No:	2ZR2V20768	Chassis No:	ZWR900091172
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	30

Remarks:	PERSON IN CHARGE CELIA HP. 92740999 AVCLAIMS@MYCARWORKSHOP.COM.SG
Present Location:	ACCORD AUTO SERVICES PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	15,742.10
Miscellaneous Items	235.00
Labour	6,180.00
Paintwork Labour	2,800.00
Towing	0.00
Gross Total (S\$)	24,957.10
+ GST 9.00% (S\$)	2,246.14
Nett Amount (S\$)	27,203.24

This claim is handled by: LAI YEAN KUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Nov 2024)
 Parts: M1-MPV TOYOTA NOAH HYBRID 1.8 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Accord Auto Services Pte Ltd/SNL4789C/08/11/2024 13:18
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front Windscreen <i>cm</i>	0.00	0.00	*880.00 F
2	1		*Front Windscreen Moulding <i>ur</i>	0.00	0.00	*60.00 F
3	1		*Front Windscreen Rain Sensor Tap ?	0.00	0.00	-
4	1		*Front Bonnet <i>bu</i>	0.00	0.00	*1,100.00 F
5	1		*Front Bonnet Stopper <i>ur</i>	0.00	0.00	-
6	1		*Front Bonnet Seal/Rubber <i>ur</i>	0.00	0.00	-
7	1		*Front Bonnet Insulator <i>cm</i>	0.00	0.00	-
8	1		*Front Bonnet Stand <i>X</i>	0.00	0.00	-
9	1		*Front Bonnet Stand Clip <i>X</i>	0.00	0.00	-
10	1		*Front Bonnet Lock <i>st</i>	0.00	0.00	*70.00 F
11	2		*Front Bonnet Hinge <i>st</i>	0.00	0.00	*120.00 F
12	1		*Front Wiper Garnish <i>de</i>	0.00	0.00	-
13	1		*Front Grille Top <i>st</i>	0.00	0.00	*140.00 F
14	1		*Front Grille Emblem <i>mr</i>	0.00	0.00	*50.00 F
15	1		*Front Grille Chrome Assy <i>cm</i>	0.00	0.00	*350.00 F
16	1		*Front Grille Base <i>cm</i>	0.00	0.00	-
17	1		*Front Radar ?	0.00	0.00	*650.00 F
18	1		*Front Bumper <i>de</i>	0.00	0.00	*450.00 F
19	2		*Front Bumper Side Retainer <i>cm</i>	0.00	0.00	*96.00 F
20	1		*Front Bumper Side Lower Chrome Moulding <i>sur</i>	0.00	0.00	-
21	1		*Front Bumper Lower Lip ?	0.00	0.00	-
22	1		*Front Bumper Under Cover	0.00	0.00	-
23	1		*Front Reinforcement Bar <i>st</i>	0.00	0.00	*250.00 F
24	1		*Front Lock Brace Panel <i>st</i>	0.00	0.00	-
25	2		*Front Headlamp <i>bu</i>	0.00	0.00	*2,600.00 F
26	2		*Front Headlamp Lower Bracket <i>bu</i>	0.00	0.00	-
27	2		*Front Headlamp Chrome Moulding <i>cm</i>	0.00	0.00	-
28	1		*Horn <i>X</i>	0.00	0.00	*65.00 F
29	1		*Support Panel <i>st</i>	0.00	0.00	-
30	1		*Support Panel Top Garnish <i>cm</i>	0.00	0.00	-
31	2		*Front Fender <i>st</i>	0.00	0.00	*800.00 F
32	2		*Front Fender Shield <i>de</i>	0.00	0.00	-
33	2		*Front Fender Side Cover	0.00	0.00	-
34	1		*Front LH Fender Inner Panel <i>repair</i>	0.00	0.00	-
35	1		*Aircon Condenser <i>st</i>	0.00	0.00	*550.00 F
36	1		*Aircon Condenser Pipe ?	0.00	0.00	-
37	1		*Aircon Condenser Hose ?	0.00	0.00	-
38	1		*Radiator <i>st</i> <i>photo</i>	0.00	0.00	*600.00 F
39	1		*Radiator Top Hose	0.00	0.00	-
40	1		*Radiator Lower Hose ?	0.00	0.00	-
41	2		*Radiator Stopper Upper <i>X</i>	0.00	0.00	-
42	2		*Radiator Stopper Lower ?	0.00	0.00	-
43	1		*Radiator Fan Motor , Blade & Cowling	0.00	0.00	*700.00 F
44	1		*Washer Tank <i>de</i>	0.00	0.00	*55.00 F
45	1		*Washer Tank Cap	0.00	0.00	-

Accord Auto Services Pte Ltd/SNL4789C/08/11/2024 13:18. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Part No.	Particulars	%Disc	%Depr	Amount
	*Spare Tank <i>de</i>	0.00	0.00	*175.00 F
	*Spare Tank Cap <i>X</i>	0.00	0.00	-
	*Airduct Hose @ Fix At Suuport Panel <i>?</i>	0.00	0.00	-
	*Air Cleaner Box Assy <i>cm</i>	0.00	0.00	-
	*Battery Tray <i>cm</i>	0.00	0.00	-
	*Battery Tray Bracket <i>?</i>	0.00	0.00	-
	*Fuse Box - Cover <i>?</i>	0.00	0.00	-
	*Fuse Box <i>?</i>	0.00	0.00	-
	*Engine Mounting Set <i>?</i>	0.00	0.00	-
	*Intake Manifold <i>?</i>	0.00	0.00	*380.00 F
	*Air Intake Resonator <i>?</i>	0.00	0.00	-
	*Hybird Coolant Hose <i>?</i>	0.00	0.00	-
	*Injector Harnes <i>?</i>	0.00	0.00	-
	*Fuel Injector <i>?</i>	0.00	0.00	-
	*Alternator <i>?</i>	0.00	0.00	-
	*Starter <i>?</i>	0.00	0.00	-
	*Aircon Compressor <i>?</i>	0.00	0.00	-
	*Engine Bay Harness <i>?</i>	0.00	0.00	-
	*Dashboard <i>cm</i>	0.00	0.00	-
	*LH Airbag <i>AG</i>	0.00	0.00	*1,450.00 F
	*RH Airbag <i>AG</i>	0.00	0.00	*1,600.00 F
	*LH Roof Airbag <i>AG</i>	0.00	0.00	-
	*RH Roof Airbag <i>AG</i>	0.00	0.00	-
	*Roof Linning <i>de</i>	0.00	0.00	-
	*Front LH Seat Belt <i>AG</i>	0.00	0.00	-
	*Front LH Seat Belt Bucket <i>X</i>	0.00	0.00	-
	*Front RH Seat Belt <i>AG</i>	0.00	0.00	-
	*Front RH Seat Belt Bucket <i>X</i>	0.00	0.00	-
	*Airbag Sensor <i>AG</i>	0.00	0.00	*360.00 F
	*Airbag Control Unit <i>AG</i>	0.00	0.00	-
	*Front Bumper Sponge <i>cm</i>	0.00	0.00	-
	*Front Reinforcement Arm <i>4</i>	0.00	0.00	-
	*Front Lower Reinforcement <i>?</i>	0.00	0.00	-
	*Front Headlamp HID/LED Control Unit <i>cm</i>	0.00	0.00	-
	*Front Headlamp Control Unit <i>?</i>	0.00	0.00	-
	*Foglight <i>RH-cm / LH-X</i>	0.00	0.00	*760.00 F
	*Front Bumper Sensor <i>?</i>	0.00	0.00	-
	*Front Bumper Sensor Harness <i>?</i>	0.00	0.00	-
	*Front LH Radiator Airduct <i>cm</i>	0.00	0.00	-
	*Front RH Radiator Airduct <i>cm</i>	0.00	0.00	-

F=Franchise part.

Sub Total (S\$)	14,311.00
+ Margin on L,N Items 10.00% (S\$)	1,431.10
Total Parts (S\$)	15,742.10

Accord Auto Services Pte Ltd/SNL4789C/08/11/2024 13:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty Particulars

Amount

Miscellaneous Items

1	1	FRONT BOTH SIDE FENDER SHIELD CLIPS <i>NA</i>	<i>20</i>	40.00
2	1	FRONT BUMPER & GRILLE CLIPS <i>NA</i>		40.00
3	1	FRONT WINDSCREEN SEALANT <i>NA</i>	<i>40</i>	60.00
4	1	NUMBER PLATE WITH FRAME <i>CR</i>	<i>35</i>	45.00
5	1	RADIATOR TOP GARNISH & UNDER ENGINE COVER CLIPS <i>NA</i>	<i>40</i>	50.00
Sub Total (\$\$)				235.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	Spray Painting to All Affected Areas	New	<i>1900</i>	2,800.00
(*Pearl Colour Basis. Including Body On Affected Area)				

Labour Items

2	Labour Remove / Refix Accident Damages Parts To Knock , Jack, Cut Weld And Realign Accident Affected Area	New	<i>2000</i>	3,800.00
(* Including Body Alignment On Affected Area)				
3	Check Wiring System & Light	New	<i>80</i>	120.00
4	To Remove/Replace Intake Manifold	New	<i>100</i>	180.00
5	To Repair/Adjust/Realign Front Main Chassis & Crossmember	New	<i>250</i>	350.00
6	To Remove/Refix/Replace Front Both Seat Belt & Buckle	New	<i>150</i>	280.00
7	To Remove/Refix/Replace The Necessary Attachment In Connection LH & RH Airbag, Dashboard ,Steering Column,Clock Spring & Etc...	New	<i>300</i>	500.00
8	Computer Diagnostic (Reset Airbag Control Unit & Necessary In Connect)	New	<i>200</i>	300.00
9	To Remove/Replace/Refix Support Panel, Radiator & Aircon Condenser (Remove pipe,hose & Etc... Top Up Coolant, Aircon Gas & Etc...)	New	<i>180</i>	280.00
10	Computer Diagnostic After Repair(*Bumper Sensor & etc...)	New	<i>250</i>	350.00
11	To Remove/ Refix/ Reinstall Front Windscreen	New		100.00
Gross Labour Cost (\$\$)				8,980.00

Accord Auto Services Pte Ltd/SNL4789C/08/11/2024 13:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Case
Hp90010068
18 clasp
4/5
11/11/24
EXEKS-TBA
Revet
Pay after repair