

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG124060263/AVH3M4**Date:** 05/08/2025REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	DMCG24000328
Claimant Vehicle No :	SMQ9094B	Insured Vehicle No :	WD6337X
Date of Loss:	22/06/2024	Nature of Claim:	TP
		Claim No:	CDMCG24001549

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ9094B	Engine No:	2NR5377259
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3801182698
Reg. Date:	10/12/2019 (Man. Year: 2019)	Odometer:	59393 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,467.60	14,460.25	7,007.35	32.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,810.00	3,230.00	2,580.00	44.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,277.60	17,690.25	9,587.35	35.15
Approved Total (Overridden) (S\$)		14,150.00		
(S\$)	27,277.60	14,150.00	13,127.60	48.13
+ GST 9.00/9.00% (S\$)	2,454.98	1,273.50	1,181.48	48.13
Nett Amount (S\$)	29,732.58	15,423.50	14,309.08	48.13

INSPECTION

Date of Assignment:	26/06/2024	
Date Inspected:	27/06/2024	Inspected At:
Estimated Period of Repair:	14.0 days	

KANG CAR REPAIRERS PTE LTD
NO.1 KAKI BUKIT AVE 6
#02-06 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2025)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ9094B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	533.90 FL	*533.90 FL
2	1		*FRT BUMPER REINFORCEMENT	Not Necessary	432.50 FL	*- FL
3	1		*FRT BUMPER SIDE RETAINER RH	Cracked	108.70 FL	*108.70 FL
4	1		*FRT BUMPER GRILLE	Not Necessary	384.90 FL	*- FL
5	1		*FRT BUMPER TOWING COVER	Missing	78.00 FL	*78.00 FL
6	1		*FRT GRILLE	Not Necessary	204.20 FL	*- FL
7	1		*FRT FOG LAMP RH	Not Necessary	346.20 FL	*- FL
8	1		*FRT FOG LAMP COVER RH	Not Necessary	90.50 FL	*- FL
9	1		*FRT FENDER RH	Distorted	827.50 FL	*827.50 FL
10	1		*FRT FENDER COWLING RH	Deformed	222.80 FL	*222.80 FL
11	1		*FRONT FENDER INNER ENCLOSER RH	Deformed	141.30 FL	*141.30 FL
12	1		*HEADLAMP RH	Cracked	1,393.40 FL	*1,393.40 FL
13	1		*FRT DOOR RH	Distorted	1,183.30 FL	*1,183.30 FL
14	2		*FRT DOOR HINGE	Bent	240.00 FL	*240.00 FL
15	1		*FRT DOOR CHECK RH	Damaged	199.40 FL	*199.40 FL
16	1		*FRT DOOR RUBBER RH	Cut	221.40 FL	*221.40 FL
17	1		*FRT DOOR OUTER MOULDING RH	Not Necessary	81.70 FL	*- FL
18	1		*FRT DOOR GLASS CHANNEL RH	Not Necessary	132.30 FL	*- FL
19	1		*FRT DOOR SIDE MIRROR RH	Cracked	1,360.50 FL	*1,360.50 FL
20	1		*FRT DOOR SIDE MIRROR COVER RH	Missing	118.50 FL	*118.50 FL
21	1		*FRT RH DOOR LOCK	Damaged	655.30 FL	*655.30 FL
22	1		*FRT DOOR OUTER HANDLE RH	Not Necessary	478.70 FL	*- FL
23	1		*FRT RH DOOR KEY LOCK COVER	Not Necessary	65.60 FL	*- FL
24	1		*FRT DOOR RH TRIM	Cracked	942.30 FL	*942.30 FL
25	1		*FRT DOOR REGULATOR RH	Damaged	299.00 FL	*299.00 FL
26	1		*FRT DOOR REGULATOR MOTOR RH	Not Necessary	765.50 FL	*- FL
27	1		*FRT RH DOOR BLACK TAPE	Necessary	82.00 FL	*82.00 FL
28	1		*REAR DOOR RH	Distorted	1,013.40 FL	*1,013.40 FL
29	2		*REAR DOOR HINGE RH	Bent	240.00 FL	*240.00 FL
30	1		*REAR DOOR CHECK RH	Damaged	199.40 FL	*199.40 FL
31	1		*REAR DOOR LOCK RH	Damaged	607.90 FL	*607.90 FL
32	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	159.80 FL	*- FL
33	1		*REAR DOOR HANDLE COVER RH	Not Necessary	65.60 FL	*- FL
34	1		*REAR DOOR GLASS REGULATOR RH	Damaged	209.40 FL	*209.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*REAR DOOR GLASS REGULATOR RH MOTOR	Not Necessary	996.60 FL	*- FL
36	1		*REAR DOOR GLASS CHANNEL RH	Not Necessary	108.70 FL	*- FL
37	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	81.70 FL	*- FL
38	1		*REAR DOOR TRIM RH	Cracked	805.10 FL	*805.10 FL
39	1		*REAR DOOR RUBBER RH	Cut	210.60 FL	*210.60 FL
40	1		*REAR DOOR RH BLACK TAPE	Necessary	76.00 FL	*76.00 FL
41	1		*REAR FENDER RH	Distorted	1,120.10 FL	*1,120.10 FL
42	1		*REAR FENDER MUDFLAP RH	Deformed	101.80 FL	*101.80 FL
43	1		*REAR FENDER INNER TRIM RH	Not Necessary	356.40 FL	*- FL
44	1		*REAR BUMPER	Deformed	570.90 FL	*570.90 FL
45	1		*REAR BUMPER SIDE RETAINER RH	Cracked	167.90 FL	*167.90 FL
46	1		*REAR BUMPER RETAINER -SMALL	Not Necessary	65.00 FL	*- FL
47	1		*FRT SHOCK ABSORBER RH	Not Necessary	453.60 FL	*- FL
48	1		*FRT LOWER ARM RH	Bent	1,321.50 FL	*965.00 FL
49	1		*FRT KNUCKLE ARM RH	Damaged	717.50 FL	*717.50 FL
50	1		*FRT WHEEL HUB RH	Damaged	644.10 FL	*644.10 FL
51	1		*FRT BEARING RH	Damaged	210.60 FL	*210.60 FL
52	1		*REAR SPORTS RIM RH	Not Necessary	1,891.90 FL	*- FL
53	1		*FRT SPORTS RIM RH	Cut	1,418.93 FS	*1,000.00 FS
54	1		*SET FRT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
55	1		*SET FRT BUMPER GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
56	2		*FRT BUMPER L PLATE BRACKET	Not Necessary	70.00 FS	*- FS
57	1		*SET FRT GRILLE CLIPS	Not Necessary	40.00 FS	*- FS
58	1		*SET FRT FENDER COWLING CLIPS RH	Necessary	40.00 FS	*30.00 FS
59	1		*FRT DOOR STICKER RH	Necessary	280.00 FS	*220.00 FS
60	1		*REAR RH DOOR STICKER	Necessary	280.00 FS	*220.00 FS
61	1		*SET REAR FENDER MUDFLAP CLIPS RH	Necessary	30.00 FS	*10.00 FS
62	1		*REAR FENDER STICKER	Necessary	290.00 FS	*200.00 FS
63	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	40.00 FS	*- FS
64	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
65	1		*REAR WINDSCREEN INNER SEAL RUBBER	Necessary	60.00 FS	*30.00 FS
66	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
67	2		*REAR BUMPER L PLATE BRACKET	Necessary	70.00 FS	*50.00 FS
68	1		*SET REAR BUMPER STICKER	Necessary	280.00 FS	*250.00 FS
69	1		*FRT TYRE RH	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	27,463.83	18,577.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,996.23	4,116.75
Total Parts (\$\$)	21,467.60	14,460.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT FRT DOOR GLASS	New	100.00	40.00
3	TO REMOVE AND REFIX REAR DOOR GLASS	New	100.00	40.00
4	TO REMOVE AND REFIT SEAT CUSHION	New	200.00	0.00
5	TO REMOVE AND REFIT FRT AND REAR DOOR TRIM	New	100.00	60.00
6	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
7	TO REPLACE FRT DOOR STICKERS	New	80.00	0.00
8	TO REPLACE REAR DOOR STICKERS	New	80.00	0.00
9	TO REPLACE REAR FENDER STICKER	New	80.00	0.00
10	TO REPLACE REAR BUMPER STICKER	New	80.00	0.00
11	TO REMOVE AND REFIT UNDERCARRIAGE	New	300.00	200.00
12	TO CHECK WHEEL ALIGNMENT	New	120.00	80.00
13	TO SPRAY PANEL SEALANT	New	100.00	60.00
14	TO SPRAY PAINTING	New	2,000.00	1,200.00
15	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS	New	2,300.00	1,400.00
Gross Labour Cost (\$\$)			5,810.00	3,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >