

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24110200/DNP3M4**Date:** 21/03/2025**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001422826		
Claimant Vehicle No :	SHB2883A	Insured Vehicle No :	SBQ4029D		
Date of Loss:	08/11/2024	Nature of Claim:	TP	Claim No:	379832

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB2883A	Engine No:	2ZR2C14829
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FUX03080419
Reg. Date:	31/05/2019 (Man. Year: 2018)	Odometer:	659688 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	LAUFENN 5 mm	Rear Left Side:	LAUFENN 5 mm
Front Right Side:	LAUFENN 5 mm	Rear Right Side:	LAUFENN 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,157.82	5,058.25	10,099.57	66.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,540.00	2,090.00	3,450.00	62.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,697.82	7,148.25	13,549.57	65.46
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	20,697.82	5,700.00	14,997.82	72.46
+ GST 9.00/9.00% (S\$)	1,862.80	513.00	1,349.80	72.46
Nett Amount (S\$)	22,560.62	6,213.00	16,347.62	72.46

INSPECTION

Date of Assignment:	12/11/2024		
Date Inspected:	12/11/2024	Inspected At:	BIFROST AUTO PTE LTD - LOYANG (HQ) 59 LOYANG DRIVE LEVEL 4 ROOM 7 SINGAPORE 508969
Estimated Period of Repair:	6.0 days		

Adjuster: BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2025)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB2883A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	503.04 FL	*- FL
2	1		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER SIDE CLIP	Not Necessary	25.00 FL	*- FL
4	1		*REAR BUMPER UNDER SIDE COVER (LH)	Not Necessary	232.00 FL	*- FL
5	1		*REAR FENDER, LH	Dented	992.04 FL	*992.04 FL
6	1		*PANEL SUB-ASSY, REAR DOOR, LH	Dented	1,258.30 FL	*1,258.30 FL
7	1		*REAR DOOR HINGE UPPER	Not Necessary	82.30 FL	*- FL
8	1		*REAR DOOR HINGE LOWER	Not Necessary	82.30 FL	*- FL
9	1		*REAR DOOR CHECK	Not Necessary	153.00 FL	*- FL
10	1		*REAR DOOR INNER LOCK	Not Necessary	644.70 FL	*- FL
11	1		*MOTOR, POWER WINDOW REGULATOR REAR, LH	Not Necessary	941.80 FL	*- FL
12	1		*REGULATOR, FRONT DOOR WINDOW REAR, LH	Not Necessary	228.40 FL	*- FL
13	1		*REAR DOOR RUBBER SEAL OUTER	Not Necessary	257.90 FL	*- FL
14	1		*PANEL SUB-ASSY, FRONT DOOR, LH	Dented	1,264.00 FL	*1,264.00 FL
15	1		*FRONT DOOR INNER LOCK	Not Necessary	688.80 FL	*- FL
16	1		*FRONT DOOR HINGE UPPER	Not Necessary	91.20 FL	*- FL
17	1		*FRONT DOOR HINGE LOWER	Not Necessary	91.20 FL	*- FL
18	1		*FRONT DOOR CHECK	Not Necessary	153.52 FL	*- FL
19	1		*FRONT DOOR WEATHER STRIP	Not Necessary	457.90 FL	*- FL
20	1		*MOTOR ASSY, POWER WINDOW FRT, LH	Not Necessary	941.80 FL	*- FL
21	1		*REGULATOR, FRONT DOOR WINDOW FRT, LH	Not Necessary	228.40 FL	*- FL
22	1		*MIRROR ASSY, OUTER REAR VIEW, LH	Not Necessary	1,728.70 FL	*- FL
23	1		*ROCKER PANEL OUTER GARNISH	Repair	576.00 FL	*- FL
24	1		*REAR TYRE RIM (LH)	Cut	1,555.00 FL	*1,555.00 FL
25	1		*REAR WHEEL CAP (LH)	Not Necessary	177.70 FL	*- FL
26	1		*REAR WHEEL BEARING HUB ASSY	Not Necessary	610.20 FL	*- FL
27	1		*REAR SHOCK ABSORBER	Not Necessary	118.30 FL	*- FL
28	1		*REAR SHOCK ABSORBER MOUNTING	Not Necessary	125.30 FL	*- FL
29	1		*REAR LOWER ARM	Not Necessary	497.50 FL	*- FL
30	1		*REAR UPPER ARM	Not Necessary	356.80 FL	*- FL
31	1		*REAR KNUCKLE ARM	Not Necessary	810.60 FL	*- FL
32	1		*REAR STABILIZER BAR	Not Necessary	311.50 FL	*- FL
33	1		*REAR STABILIZER LINK	Not Necessary	151.60 FL	*- FL
34	1		*REAR TRAILING ARM	Not Necessary	314.20 FL	*- FL
35	1		*REAR ASSIST ARM	Not Necessary	342.20 FL	*- FL
36	1		*FENDER SUB-ASSY, FRONT LH	Dented	1,111.93 FL	*1,111.93 FL
37	1		*FRONT FENDER SHIELD	Deformed	255.00 FL	*255.00 FL
38	1		*FRONT FENDER SHIELD CLIP	Necessary	14.90 FL	*14.90 FL
39	1		*FRONT FENDER HYBRID EMBLEM, LH	Necessary	86.50 FL	*86.50 FL
40	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FS	*75.00 FS
41	1		*REAR DOOR COMFORT & APPS STICKER	Necessary	80.00 FS	*80.00 FS
42	1		*REAR TYRE (LH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,854.53	6,692.67
- List Item Discount on L Items 20.00/25.00% (\$\$)	3,696.71	1,634.42

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					15,157.82	5,058.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,000.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	100.00	30.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX UNDERCARRIAGE (RR)	New	400.00	0.00
8	REMOVE/REFIX FUEL TANK	New	80.00	0.00
9	TRANSFER OF DOOR MECHANISM FRONT	New	80.00	60.00
10	RE-SET FRT POWER WINDOW SYSTEM	New	200.00	0.00
11	TRANSFER OF DOOR MECHANISM REAR	New	80.00	60.00
12	RE-SET REAR POWER WINDOW SYSTEM	New	200.00	0.00
13	FOUR WHEEL ALIGNMENT	New	120.00	60.00
14	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			5,540.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >