

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110201/UPA3Q2
Date: 14/05/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_05
Claimant Vehicle No : GBK5024S Insured Vehicle No : YR1144X
Date of Loss: 09/11/2024 Nature of Claim: TP Claim No: MFL2024D0013434

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBK5024S
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5DR MT (M) Engine No: 1KDB039993
Reg. Date: 24/08/2020 (Man. Year: 2020) Chassis No: JTFHT02P409990075
Colour: White Odometer: 177079 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,650.45	4,013.75	6,636.70	62.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,020.00	1,300.00	2,720.00	67.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,670.45	5,313.75	9,356.70	63.78
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	14,670.45	4,200.00	10,470.45	71.37
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 12/11/2024
Date Inspected: 12/11/2024 Inspected At: Carsmith Private Limited (HQ)
8 Kaki Bukit Ave 4, #04-35 Premier
Singapore 415875
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 May 2025)	
Parts:	N/A	TOYOTA HIACE 3.0 D TURBO 5DR MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK5024S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented / Bent	1,890.00 FL	*1,890.00 FL
2	1		*TAILGATE RUBBER TOP GARNISH	Not Necessary	102.70 FL	*- FL
3	1		*TAILGATE RUBBER	Not Necessary	328.50 FL	*- FL
4	1		*TAILGATE LOCK	Serviceable	285.10 FL	*- FL
5	2		*TAILGATE HINGE	Not Necessary	190.50 FL	*- FL
6	2		*TAILGATE ABSORBER	Not Necessary	590.00 FL	*- FL
7	1		*TAILGATE CENTER GARNISH	Grazed	186.50 FL	*186.50 FL
8	1		*TAILGATE HANDLE	Not Necessary	255.00 FL	*- FL
9	1		*TAILGATE INNER BOARD	Not Necessary	335.20 FL	*- FL
10	1		*TAILGATE LOCK ACTUATOR	Not Necessary	430.60 FL	*- FL
11	1		*TAILGATE EMBLEM LOGO	Necessary	108.00 FL	*85.00 FL
12	1		*TAILGATE WINDSCREEN MOULDING	No such part	218.50 FL	*- FL
13	1		*TAILGATE WINDSCREEN	Shattered	1,250.00 FL	*1,099.00 FL
14	2		*TAILGATE STOPPER	Not Necessary	80.00 FL	*- FL
15	1		*REAR END PANEL INNER	Repair	912.70 FL	*- FL
16	1		*REAR END PANEL OUTER	Dented	486.50 FL	*486.50 FL
17	1		*REAR FLOOR BOARD PANEL	Not Necessary	2,381.40 FL	*- FL
18	1		*INNER BUMPER PLATE	Not Necessary	325.00 FL	*- FL
19	1		*REAR BUMPER	Dented	698.00 FL	*698.00 FL
20	2		*REAR BUMPER SIDE RETAINER	Not Necessary	161.60 FL	*- FL
21	4		*REAR BUMPER LOWER SUPPORT BRACKET	Serviceable	244.80 FL	*- FL
22	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
23	1		*SET REAR NUMBER PLATE	Serviceable	80.00 FS	*- FS
24	1		*TAILGATE STICKER 70KM/H	Necessary	45.00 FS	*10.00 FS
25	1		*SET COMPANY STICKER AND WRAP STICKER	Necessary	800.00 FS	*600.00 FS
26	1		*SET REVERSE SENSOR	Serviceable	480.00 FS	*- FS
27	1		*SET REVERSE CAMERA	Not Necessary	480.00 FS	*- FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,515.60	5,125.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,865.15	1,111.25
Total Parts (\$\$)	10,650.45	4,013.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM	New	300.00	20.00
2	REMOVE AND REFIX REVERSE SENSOR	New	120.00	30.00
3	REMOVE AND REFIX ACCIDENT AFFECTED AREA LINING TRIM AND GARNISH	New	300.00	0.00
4	PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,600.00	600.00
5	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	1,600.00	600.00
6	APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	New	100.00	50.00
Gross Labour Cost (\$\$)			4,020.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >