

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL	INSURANCE LTD	Ref:	CS3/FCl24110204/Enp3m4	
	16 RAFFLES QUAY		Date:	12/11/2024	
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2	
1. Policy Particulars :- PRE-REPAIR SURVEY					
	Insured Veh.	SHC 7588P	Veh. Inspected	SLF 292A	
	Policy No.	D-24101860MFCT	Coverage	0	
	Claim No.	D24009876MFCT	Excess	\$0.00	
	Assign From	JOANNE	Assign Date	11/11/2024	
2. Vehicle Details					
	Make & Model	HONDA VEZEL	C.C	1496	
	Engine No.	L15B4430838	Year of Reg.	20/02/2018	
	Chassis No.	RU11230830	Colour	WHITE	
	Odometer	81211 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.		Conditions of Tyres			
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60R16	MICHELIN	6	
	L/H Front Tyre	215/60R16	MICHELIN	6	
	R/H Rear Tyre	215/60R16	MICHELIN	6	
	L/H Rear Tyre	215/60R16	MICHELIN	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5. General Information					
	Accident Date	08/11/2024	Inspection Date	12/11/2024 (10:06)	
	Survey held at	urvey held at JHK AUTO SERVICES - 3014 UBI ROAD 1 #01-322 SINGAPORE 408702			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					
D)MARKET VALUE:\$52,000.00 (EST) E)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					

CTY

5b.

CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days

Estimate Days of Repair