



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YR 969P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	TAIL LAMP @\$365.80	O/S CRACKED	731.60	365.80
1	REAR NUMBER PLATE LAMP	NOT NECESSARY	95.20	-
1	REAR NUMBER PLATE SUPPORT BRACKET	NOT NECESSARY	195.00	-
1	REAR LOWER END PANEL	TO REPAIR SEE LABOUR	1,684.10	-
	LESS 10% DISCOUNT		-270.59	-36.58
			2,435.31	329.22
<u>SPECIAL NETT ITEMS</u>				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	REAR CARRIER FLOOR WOODEN MEMBER (SN)	NOT NECESSARY	1,200.00	-
1	TAIL GATE '70KM/H' STICKER (SN)	NOT NECESSARY	20.00	-
1	TAIL GATE 22 PAX (SN)	NOT NECESSARY	20.00	-
1	REAR REINFORCEMENT LOWER(SPECIAL TYPE) (SN)	TO REPAIR SEE LABOUR	1,200.00	-
1	REAR REINFORCEMENT LOWER REFLECTIVE STICKER (SN)	NECESSARY	250.00	30.00
2	HYDRAULIC FLUID @\$60.00 (SN)	NOT NECESSARY	120.00	-
2	REAR HYDRAULIC "L" ARM @\$3,500.00 (SN)	NOT NECESSARY	7,000.00	-
2	REAR HYDRAULIC "T" ARM @\$4,100.00 (SN)	NOT NECESSARY	8,200.00	-
1	CRANE MAIN LIFTING BEAM HYDRAULIC CYLINDER JACK (SN)	NOT NECESSARY	1,800.00	-
2	TAILAMP LOWER SUPPORT BRACKET @\$280.00 (SN)	O/S BENT	560.00	280.00
1	TAILAMP LOWER SUPPORT BRACKET BEAM (SN)	CRACKED	280.00	200.00
			20,700.00	510.00
<u>LABOUR</u>				
	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK. INCLUSIVE OF THE REPAIR OF REAR LOWER END PANEL AND REAR REINFORCEMENT LOWER(SPECIAL TYPE).		1,600.00	400.00
	TO PUTTY, SPRAY PAINT, POLISH WAX.		1,000.00	250.00
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	-

Report Ref No. CS/INC24110205/Avh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE /INSTALL REAR LIFTING PLATFORM,ALIGN AND ADJUSTMENT.	NOT NECESSARY	850.00	-
			3,700.00	650.00
GRAND TOTAL			26,835.31	1,489.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,200.00

Report Ref No. CS/INC24110205/Avh3m4(N)

TOTAL FOR SPARE PARTS: \$23,135.31 \$ 839.22
TOTAL FOR LABOUR : \$ 3,700.00 \$ 650.00
TOTAL REPAIR COST: \$26,835.31 \$ 1,489.22

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.