

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24060265/AMA3Q2**Date:** 09/12/2024**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100510715
Claimant Vehicle No :	SMD5241M	Insured Vehicle No :	SLQ5573Z
Date of Loss:	13/06/2024	Nature of Claim:	TP
		Claim No:	0385974647SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD5241M	Engine No:	G4FGJU247246
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (AMS) (A)	Chassis No:	KMHD841CMJU738641
Reg. Date:	24/08/2018 (Man. Year: 2018)	Odometer:	105363 km
Colour:	Grey		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,119.04	1,943.20	9,175.84	82.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,890.00	1,100.00	5,790.00	84.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,009.04	3,043.20	14,965.84	83.10
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	18,009.04	2,400.00	15,609.04	86.67
+ GST 9.00/9.00% (S\$)	1,620.81	216.00	1,404.81	86.67
Nett Amount (S\$)	19,629.85	2,616.00	17,013.85	86.67
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
(S\$)		2,856.00		
Liabe Amount (50.00%) (S\$)		1,428.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		1,459.00		
Global Sum Settlement (S\$)		1,400.00		

INSPECTION

Date of Assignment:	24/06/2024	JL Perfect Autowork Pte Ltd (HQ)
Date Inspected:	24/06/2024 Inspected At:	8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
Estimated Period of Repair:	4.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Torn	757.40 FL	*474.00 FL
2	1		*REAR BUMPER REFLECTOR RH	Not Necessary	72.50 FL	*- FL
3	1		*REAR BUMPER MUDFLAP RH	Not Necessary	159.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Not Necessary	114.60 FL	*- FL
5	1		*REAR FENDER RH	Repair	1,470.00 FL	*- FL
6	1		*REAR FENDER COWLING RH	Not Necessary	250.00 FL	*- FL
7	1		*REAR WINDSCREEN MOULDING	Not Necessary	180.00 FL	*- FL
8	1		*TAILLAMP RH	Not Necessary	876.80 FL	*- FL
9	1		*REAR WHEEL RIM RH	Cut	896.00 FS	*450.00 FS
10	1		*REAR AXLE	Not Necessary	2,140.00 FL	*- FL
11	1		*REAR SHOCK ABSORBER RH	Not Necessary	475.00 FL	*- FL
12	1		*REAR WHEEL HUP WITH BEARING RH	Not Necessary	525.00 FL	*- FL
13	1		*REAR ABS SENSOR RH	Not Necessary	325.00 FL	*- FL
14	1		*REAR DOOR RH	Dented	1,280.00 FL	*1,280.00 FL
15	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	198.00 FL	*- FL
16	1		*REAR DOOR LOCK CATCH RH	Not Necessary	45.00 FL	*- FL
17	1		*REAR DOOR INNER LOCK RH	Not Necessary	425.00 FL	*- FL
18	1		*REAR DOOR GLASS REGULATOR GEAR MOTOR RH	Not Necessary	770.00 FL	*- FL
19	1		*REAR DOOR GLASS FRAME BLACK STICKER RH	Necessary	128.00 FS	*60.00 FS
20	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	118.00 FL	*- FL
21	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	950.00 FL	*- FL
22	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
23	1		*SET TAILLAMP CLIP RH	Not Necessary	50.00 FS	*- FS
24	1		*SET REAR DOOR TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
25	1		*REAR FENDER SEALANT RH	Not Necessary	80.00 FS	*- FS
26	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*REAR WINDSCREEN GLASS INNER SHIELD RH	Not Necessary	60.00 FS	*- FS
28	2		*REAR WHEEL TYRE	Not Necessary	760.00 FS	*- FS
29	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,345.30	2,294.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,226.26	350.80
Total Parts (\$\$)	11,119.04	1,943.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING REMOVING AND REPLACING PARTS	New	2,000.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	600.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	250.00	0.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	650.00	0.00
6	FOUR WHEEL ALIGNMENT	New	120.00	0.00
7	TRANSFER REAR DOOR MECHANISM	New	80.00	60.00
8	REMOVE & REFIX AUDIO SPEAKER	New	150.00	0.00
9	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
10	REMOVE & REFIX REAR WINDSCREEN	New	120.00	0.00
11	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
12	RESET ABS LIGHT	New	350.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			6,890.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >