

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2401658
INV Date : 04-12-2024

Reference CD/FCI24110212/Uma3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SNM 7075D
Insured Veh. SHA 7260U
Claim No. D24009911MFCT/CTPL/TPD 2
Policy No. D-24101861MFCT
Accident Date 09/11/2024
Inspection Date 18/11/2024

Description	Amount
Survey Inspection	200.00
Resurvey Inspection	0.00
Digital Photographs	0.00
Transportation	0.00
Sub-Total	200.00
GST (9%)	18.00
Grand Total	218.00

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24110212/Uma3q2
16 RAFFLES QUAY	Date:	04/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHA 7260U	Veh. Inspected	SNM 7075D
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009911MFCT/CTPL/TPD 2	Excess	\$0.00
Assign From	NEO JIE SI	Assign Date	12/11/2024

2. Vehicle Details

Make & Model	SUBARU FORESTER 2.0I-L CVT AWD SR	C.C	1995
Engine No.	FB20YE42383	Year of Reg.	17/09/2018
Chassis No.	JF1SJ5KC5JG111819	Colour	GREY
Odometer	82765 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R18	GOODYEAR	6
L/H Front Tyre	225/55R18	GOODYEAR	6
R/H Rear Tyre	225/55R18	GOODYEAR	6
L/H Rear Tyre	225/55R18	GOODYEAR	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/11/2024	Inspection Date	18/11/2024
Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNM 7075D

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	CUT/TORN	\$641.90	\$641.90
2	FRONT BUMPER SIDE RETAINER LH/RH @\$19.50	NOT NECESSARY	\$39.00	\$0.00
10	FRONT BUMPER CLIPS @\$3.90	NECESSARY	\$39.00	\$39.00
1	FRONT FENDER -RH	TO REPAIR SEE LABOUR	\$306.00	\$0.00
1	FRONT FENDER COWLING -RH	* CHECK ITEM *	\$126.70	\$0.00
10	FRONT FENDER COWLING CLIPS RH @\$5.40	NOT NECESSARY	\$54.00	\$0.00
	LESS 20.00% DISCOUNT		(\$241.32)	(\$136.18)
			\$965.28	\$544.72

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO KNOCK OUT DENTS ,REMOVE,REPLACE ACCIDENT PORTIONS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH .		\$500.00	\$200.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS		\$550.00	\$400.00
	ANTI RUST		\$40.00	\$0.00
	TO CHECK WIRING		\$50.00	\$20.00
			\$1,140.00	\$620.00

GRAND TOTAL			\$2,105.28	\$1,164.72
--------------------	--	--	-------------------	-------------------

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$900.00
--	---	--	--	-----------------

Report Ref No: CD/FCI24110212/Uma3q2				
---	--	--	--	--

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repossibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNM 7075D



PHOTOGRAPHS FOR VEHICLE NO. : SNM 7075D



PHOTOGRAPHS FOR VEHICLE NO. : SNM 7075D



PHOTOGRAPHS FOR VEHICLE NO. : SNM 7075D



PHOTOGRAPHS FOR VEHICLE NO. : SNM 7075D



PHOTOGRAPHS FOR VEHICLE NO. : SNM 7075D



PHOTOGRAPHS FOR VEHICLE NO. : SNM 7075D



PHOTOGRAPHS FOR VEHICLE NO. : SNM 7075D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SNM 7075D

