



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBK 2627Y

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	NOT NECESSARY	\$907.30	\$0.00
1	FRONT CABIN REAR MUDFLAP	CUT	\$307.50	\$307.50
1	FRONT LH DOOR	TO REPAIR SEE LABOUR	\$1,674.90	\$0.00
1	FRONT LH DOOR CHECKER	NOT NECESSARY	\$60.92	\$0.00
1	FRONT LH DOOR HINGE (BOTTOM)	NOT NECESSARY	\$65.70	\$0.00
1	FRONT LH DOOR HINGE (TOP)	NOT NECESSARY	\$65.70	\$0.00
1	FRONT LH DOOR INNER TRIM BOARD	NOT NECESSARY	\$823.70	\$0.00
1	FRONT LH DOOR SIGNAL LAMP	CRACKED	\$67.80	\$67.80
1	FRONT LH DOOR STEP GARNISH	CUT	\$192.30	\$192.30
1	FRONT LH DOOR WEATHER STRIP	NOT NECESSARY	\$159.10	\$0.00
1	REAR LH SIDE GATE	TO REPAIR SEE LABOUR	\$2,987.10	\$0.00
5	REAR LH SIDE GATE HINGES @\$63.20	NOT NECESSARY	\$316.00	\$0.00
	LESS 10.00% DISCOUNT		(\$762.80)	(\$56.76)
			\$6,865.22	\$510.84

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT LH DOOR '3RD' ART WORK STICKER (SN)	NECESSARY	\$400.00	\$150.00
1	FRONT LH DOOR COMPANY DECAL STICKER (SN)	NECESSARY	\$25.00	\$25.00
1	SET FRONT LH DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET FRONT LH DOOR STEP GARNISH CLIPS (SN)	NOT NECESSARY	\$30.00	\$0.00
1	FRONT LH RIM (SN)	NOT NECESSARY	\$800.00	\$0.00
1	FRONT LH TYRE (SN)	NOT NECESSARY	\$380.00	\$0.00
1	REAR LH SIDE GATE '3RD' ART WORK STICKER (SN)	NECESSARY	\$600.00	\$280.00
1	SET REAR LH SIDE GATE HINGES PIN & NUT (SN)	NOT NECESSARY	\$400.00	\$0.00
			\$2,685.00	\$455.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE	NOT NECESSARY	\$80.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$800.00	\$500.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT LH DOOR AND REAR LH SIDE GATE		\$800.00	\$200.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$80.00	\$40.00
			\$1,760.00	\$740.00
GRAND TOTAL			\$11,310.22	\$1,705.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,300.00
Report Ref No: CS/INC24110217/Aqh3m4				

TOTAL FOR SPARE PARTS: \$ 9,550.22 \$ 965.84
TOTAL FOR LABOUR : \$ 1,760.00 \$ 740.00
TOTAL REPAIR COST: \$11,310.22 \$ 1,705.84

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.