



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 1171A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
2	FRONT FORK TUBE ASSY	BENT / TWISTED	880.00	720.00
1	FORK UNDER BRACKET	BENT / TWISTED	280.00	180.00
1	FRONT RIM SHAFT	NOT NECESSARY	150.00	-
1	HEADLAMP (LED)	CRACKED	1,550.00	1,230.00
1	WINDSHIELD	SCRATCHED / CRACKED	480.00	380.00
1	SET FRONT SIGNAL	CRACKED	260.00	80.00
1	HANDLE BAR	BENT	280.00	180.00
1	SET HANDLE BAR BALANCER	CUT	155.00	38.00
1	SET HAND GRIP	NOT NECESSARY	88.00	-
1	SET MIRROR	CUT	330.00	180.00
1	BRAKE LEVER	CUT	160.00	105.00
1	FOOT STEP PANEL - R/H	CUT	180.00	166.00
1	FOOT STEP LOWER PANEL - R/H	CUT	280.00	202.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	960.00	-
1	EXHAUST FRONT COVER	MISSING	105.00	105.00
1	EXHAUST CENTER COVER	CUT	125.00	125.00
1	EXHAUST END CAP	SERVICEABLE	115.00	-
1	FAIRING ASSY	CRACKED	1,480.00	880.00
	LESS 10% DISCOUNT		-785.80	-457.10
			7,072.20	4,113.90
<u>SPECIAL NETT ITEMS</u>				
1	SET NUMBER PLATE (SN)	NECESSARY	38.00	10.00
1	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	BEARING CONE (SN)	NECESSARY	95.00	60.00
1	LOGO (SN)	NECESSARY	120.00	60.00
1	REAR BOX (SN)	CUT	580.00	480.00
1	REAR BOX BRACKET (SN)	SERVICEABLE	180.00	-

Report Ref No. CS/INC24110228/Unh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CRASH BAR (SN)	NOT FITTED	480.00	-
			1,579.00	610.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	580.00	-
	TO PROVIDE LABOUR. INCLUSIVE OF THE REPAIR OF EXHAUST ASSY.		480.00	300.00
			1,140.00	300.00
GRAND TOTAL			9,791.20	5,023.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,000.00

Report Ref No. CS/INC24110228/Unh3e2(N)

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.