12/20/24, 2:32 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110230/EPA3Q2

Date: 20/12/2024

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_03

Claimant Vehicle SMR1110K Insured Vehicle No: SNS9752M No:

Date of Loss: 10/11/2024 Nature of Claim: TP Claim No: MFL2024D0013304

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMR1110K Reg No:

Make & Model: JAGUAR XE 2.0 I4D TSS, 2.0 D (A) Engine No: 150710W0374204DTD Reg. Date: 24/11/2015 (Man. Year: 2015) Chassis No: SAJAB4AN8GA914647

Colour: Silver Odometer: 126009 km

Engine Capacity: 1999 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: Nο

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,307.50	6,322.05	1,985.45	23.90
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,150.00	510.00	640.00	55.65
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	9,457.50	6,832.05	2,625.45	27.76
	Approved Total (Overridden) (S\$)		5,450.00		
	Nett Amount (S\$)	9,457.50	5,450.00	4,007.50	42.37
	Global Sum	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment: 18/11/2024

Dickson Auto Care Centre Pte Ltd (HQ) Date Inspected: 18/11/2024 Inspected At: 29 Ubi Road 4, Dickson Auto Centre

Singapore 408619

Estimated Period of Repair: 4.0 days

CHEW HSIAO TONG Adjuster: **CHEN TSUE YEE** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

12/20/24, 2:32 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Dec 2024)

Parts: N/A JAGUAR XE 2.0 I4D TSS 2.0 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMR1110K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRONT	Broken	3,750.00 F	*2,820.00 FL
2	10		*BUMPER CLIPS	Necessary	150.00 F	*30.00 FL
3	1		*HEADLAMP ASSY RH	Broken	4,050.00 F	*3,897.00 FL
4	1		*BUMPER SIDE RETAINER FRONT RH	Broken	157.50 F	*157.50 FL
5	1		*SENSOR BRACKET FRONT	Necessary	200.00 F	*120.00 FL
F=Fra	anchise	part. L=ListIter	nDisc.	_		
				Sub Total (S\$)	8,307.50	7,024.50
			- List Item Discount on L Items	s 0.00/10.00% (S\$)	0.00	702.45
				Total Parts (S\$)	8,307.50	6,322.05
			Report was unsubmitted during this	s print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			,
1	TO REMOVE & REPLACE BUMPER FRONT HEADLAMP ASSY RH & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	New	400.00	250.00
2	TO SPRAY BUMPER FRONT	New	300.00	200.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	100.00	30.00
4	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	150.00	0.00
5	TO CARRY OUT BODY CAVITY PRESERVATION	New	100.00	0.00
6	TO TRANSFER SENSORS FRONT	New	100.00	30.00
	Gross Labour	1,150.00	510.00	
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >