

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24060267/UQH3M4

Date: 12/07/2024

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002989502
Claimant Vehicle No :	SFY56L	Insured Vehicle No :	SLQ7389B
Date of Loss:	24/06/2024	Nature of Claim:	TP
		Claim No:	364435

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFY56L	Engine No:	L15B74870094
Make & Model:	HONDA CIVIC, 1.5 TURBO VTIS CVT SR (A)	Chassis No:	MRHFC1660LT000012
Reg. Date:	18/12/2020 (Man. Year: 2020)	Odometer:	44806 km
Colour:	Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,388.20	1,950.36	5,437.84	73.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,930.00	1,560.00	2,370.00	60.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,318.20	3,510.36	7,807.84	68.98
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	11,318.20	2,800.00	8,518.20	75.26
+ GST 9.00/9.00% (S\$)	1,018.64	252.00	766.64	75.26
Nett Amount (S\$)	12,336.84	3,052.00	9,284.84	75.26

INSPECTION

Date of Assignment:	26/06/2024		
Date Inspected:	27/06/2024	Inspected At:	S M SPRAY PAINTING PTE LTD 25 KAKI BUKIT ROAD 4 #08-30 SYNERGY @ KB SINGAPORE 417800
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2024)
Parts:	143	HONDA CIVIC 1.5 TURBO VTIS CVT SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFY56L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	760.10 FL	*724.70 FL
2	1		*BOOTLID HINGE RH	Not Necessary	54.20 FL	*- FL
3	1		*BOOTLID HINGE LH	Not Necessary	54.20 FL	*- FL
4	1		*BOOTLID LOCK	Serviceable	90.40 FL	*- FL
5	1		*BOOTLID WEATHERSTRIP	Serviceable	70.40 FL	*- FL
6	1		*BOOTLID EMBLEM - CARBON FIBER	Not Necessary	246.60 FL	*- FL
7	1		*BOOTLID INNER TRIM	Not Necessary	49.90 FL	*- FL
8	1		*BOOTLID THIRD BRAKE LAMP	Not Necessary	96.30 FL	*- FL
9	1		*BOOTLID CENTER GARNISH	Not Necessary	121.80 FL	*- FL
10	1		*BOOTLAMP RH	Not Necessary	148.20 FL	*- FL
11	1		*BOOTLAMP LH	Not Necessary	148.20 FL	*- FL
12	1		*TAILLAMP OUTER RH	Not Necessary	316.20 FL	*- FL
13	1		*TAILLAMP OUTER LH	Cracked	316.20 FL	*316.20 FL
14	1		*REAR BUMPER	Torn	617.20 FL	*617.20 FL
15	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	21.50 FL	*- FL
16	1		*REAR BUMPER SIDE RETAINER LH	Bent	21.50 FL	*21.50 FL
17	1		*REAR BUMPER BRACKET RH	No such part	12.70 FL	*- FL
18	1		*REAR BUMPER BRACKET LH	No such part	12.70 FL	*- FL
19	1		*REAR PARKING SENSOR RH OUTER	Not Necessary	266.20 FL	*- FL
20	1		*REAR PARKING SENSOR RH INNER	Not Necessary	266.20 FL	*- FL
21	1		*REAR PARKING SENSOR LH OUTER	Serviceable	266.20 FL	*- FL
22	1		*REAR PARKING SENSOR LH INNER	Serviceable	266.20 FL	*- FL
23	1		*REAR PARKING SENSOR HOLDER RH OUTER	Not Necessary	72.60 FL	*- FL
24	1		*REAR PARKING SENSOR HOLDER RH INNER	Not Necessary	72.60 FL	*- FL
25	1		*REAR PARKING SENSOR HOLDER LH OUTER	Not Necessary	72.60 FL	*- FL
26	1		*REAR PARKING SENSOR HOLDER LH OUTER	Not Necessary	72.60 FL	*- FL
27	1		*REAR BUMPER REINFORCEMENT	Dented	199.20 FL	*199.20 FL
28	1		*REAR BUMPER REFLECTOR RH	Not Necessary	29.20 FL	*- FL
29	1		*REAR BUMPER REFLECTOR LH	Cut	29.20 FL	*29.20 FL
30	1		*REAR BUMPER LOWER CHROME	Scratched	136.20 FL	*136.20 FL
31	1		*REAR END PANEL	Repair	294.25 FL	*- FL
32	1		*END PANEL TOP GARNISH	Not Necessary	60.30 FL	*- FL
33	1		*END PANEL ANTENNA	Not Necessary	64.70 FL	*- FL
34	1		*END PANEL BUZZER	Not Necessary	80.10 FL	*- FL
35	1		*REAR FENDER INNER TRIM RH	Not Necessary	70.10 FL	*- FL
36	1		*REAR FENDER INNER TRIM LH	Not Necessary	70.10 FL	*- FL
37	1		*REAR FENDER RH	Not Necessary	861.20 FL	*- FL
38	1		*REAR FENDER LH	Repair	861.20 FL	*- FL
39	1		*SPARE TYRE PANEL	Not Necessary	362.40 FL	*- FL
40	1		*SPARE TYRE COMPARTMENT BOX	Not Necessary	66.10 FL	*- FL
41	1		*REAR NUMBER PLATE WITH CASING	Damaged	80.00 FS	*35.00 FS
42	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
43	1		*SET END PANEL TOP GARNISH CLIPS	Not Necessary	80.00 FS	*- FS
44	1		*SEALANT - BODY JOINT	Not Necessary	80.00 FS	*- FS
45	1		*SET BOOTLID INNER BOARD CLIPS	Not Necessary	80.00 FS	*- FS
46	1		*BOOTLID TOP SPOILER	Not Necessary	580.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*SET REAR BUMPER SIDE SPOILER	Cracked	250.00 FS	*250.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					8,927.75	2,359.20
- List Item Discount on L Items 20.00/20.00% (\$)					1,539.55	408.84
Total Parts (\$)					7,388.20	1,950.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE, REPAIR AND REPLACE PARTS FOR THE EFFECTED AREAS	New	1,600.00	600.00
2	PUTTY, BLEND AND SPRAY PAINT	New	1,500.00	800.00
3	CHECK WIRING, RE-ALIGN TAILLAMPS	New	80.00	20.00
4	REMOVE AND REINSTALL CUSHIONS, SEATS, BACKRESTS, INNER TRIM, GARNISH, ROOF LINING AND/OR UPHOLSTERY TO FACILITATE REPAIR }	New	150.00	60.00
5	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR }	New	150.00	0.00
6	REMOVE AND REINSTALL REAR TRIM COMPARTMENT }	New	150.00	0.00
7	DISMANTLE AND TRANSFER BOOTLID FITTINGS AND MECHANISM TO NEW BOOTLID TO FACILITATE REPAIR	New	180.00	50.00
8	REMOVE AND REINSTALL REAR BUMPER SENSORS	New	120.00	30.00
Gross Labour Cost (\$\$)			3,930.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >