



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110243/Unp3e2
16 RAFFLES QUAY	Date:	12/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1135C	Veh. Inspected	FBT 1214P
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009647MFCT	Excess	\$0.00
Assign From	CAROLINE	Assign Date	12/11/2024

2. Vehicle Details

Make & Model	YAMAHA NMAX 155	C.C	155
Engine No.	G3L8E0668918	Year of Reg.	17/11/2021
Chassis No.	MH3SG5680MK091936	Colour	RED
Odometer	62160 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	110-70-13	MAXXIS	6
L/H Front Tyre			
R/H Rear Tyre	130/70-13	PIRELLI	6
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/10/2024	Inspection Date	13/11/2024
Survey held at	EROFIA MOTOR WORKSHOP 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days