

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24110259/EPA3Q2
Date: 18/03/2025**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D24MFL0003405
Claimant Vehicle No :	SLH8844U	Insured Vehicle No :	PC9611Y
Date of Loss:	10/11/2024	Nature of Claim:	TP
		Claim No:	MFL2024D0013385

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH8844U	Engine No:	2ARH790790
Make & Model:	TOYOTA VELLFIRE, 2.5 CVT S/R (A)	Chassis No:	JTNGF3DH608007112
Reg. Date:	22/11/2016 (Man. Year: 2016)	Odometer:	152407 km
Colour:	White		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 5 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,242.40	10,118.85	7,123.55	41.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,200.00	1,850.00	60.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,292.40	11,318.85	8,973.55	44.22
Approved Total (Overridden) (S\$)		9,050.00		
Nett Amount (S\$)	20,292.40	9,050.00	11,242.40	55.40
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	14/11/2024		
Date Inspected:	14/11/2024	Inspected At:	Dickson Auto Care Centre Pte Ltd (HQ) 29 Ubi Road 4, Dickson Auto Centre Singapore 408619
Estimated Period of Repair:	5.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 18 Mar 2025)	
Parts: M1-MPV	TOYOTA VELLFIRE 2.5 CVT S/R (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLH8844U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRONT	Broken	967.80 F	*967.80 FL
2	10		*BUMPER CLIPS	Necessary	55.00 F	*55.00 FL
3	1		*BUMPER SIDE RETAINER LH	Broken	104.50 F	*104.50 FL
4	1		*SENSOR FRONT LH	Not Necessary	503.90 F	*- FL
5	2		*SENSOR BRACKET FRONT	Necessary	92.80 F	*92.80 FL
6	1		*HEADLAMP ASSY LH	Broken	6,443.50 F	*6,443.50 FL
7	1		*HEADLAMP ASSY COVER LH	*Check	145.30 F	*- FL
8	1		*GRILLE FRONT	Broken	2,142.10 F	*2,142.10 FL
9	1		*GRILLE BADGE (LOGO)	Necessary	118.50 F	*118.50 FL
10	1		*BONNET	Repair	1,194.60 F	*- FL
11	1		*BONNET LOCK	Not Necessary	187.20 F	*- FL
12	1		*BONNET HINGE LH	Not Necessary	81.80 F	*- FL
13	1		*BONNET HINGE RH	Not Necessary	81.80 F	*- FL
14	1		*FENDER FRONT LH	Dented	1,998.70 F	*1,998.70 FL
15	1		*FENDER LINER FRONT LH	Torn	395.00 F	*395.00 FL
16	10		*FENDER LINER CLIPS	Necessary	55.00 F	*55.00 FL
17	1		*TOW EYE COVER FRONT LH	Not Necessary	21.30 F	*- FL
18	1		*FOG LAMP FRONT LH	Not Necessary	421.30 F	*- FL
19	1		*FOG LAMP FINISHER FRONT LH (WITH CHROME)	Not Necessary	165.10 F	*- FL
20	1		*BONNET GARNISH (CHROME)	Broken	764.00 F	*764.00 FL
21	1		*WINDSCREEN MOULDING LH (OUTER)	Broken	155.10 F	*155.10 FL
22	1		*FENDER QUARTER GLASS FRONT LH	Not Necessary	325.50 F	*- FL
23	1		*WASHER TANK SCREEN	Crushed	199.80 F	*199.80 FL
24	1		*RAD SUPPORT PANEL LH	*Check	522.80 F	*- FL
25	1		*WINDSCREEN SEALANT	Not Necessary	100.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	17,242.40	13,491.80
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	3,372.95
Total Parts (\$\$)	17,242.40	10,118.85

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE BUMPER FRONT ,HEADLAMP ASSY LH,BONNET ,FENDER FRONT LH, RAD SUPPORT PANEL LH & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	New	1,200.00	450.00
2	TO SPRAY BUMPER FRONT ,BONNET ,FENDER FRONT LH & RAD SUPPORT PANEL LH	New	1,100.00	660.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	150.00	30.00
4	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	200.00	0.00
5	TO CARRY OUT BODY CAVITY PRESERVATION	New	150.00	30.00
6	TO REMOVE & REFIT FENDER QUARTER GLASS FRONT LH	New	150.00	0.00
7	TO TRANSFER SENSORS FRONT	New	100.00	30.00
			Gross Labour Cost (\$)	3,050.00
				1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >