## Note: This document has not been finalised.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 From: LKK Auto Consultants Pte Ltd

Est. Duration of Repair

: 2

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Melvin Ye Yongkang Date: 15 Nov 2024

# **Preliminary Advice**

Insured Vehicle No : SKN6266G

TP Vehicle No : GBC8817T Accident Date : 12/11/2024

Make : TOYOTA DYNA 150 MANUAL Assignment Date : 13/11/2024

Date of Inspection : 13/11/2024

Inspection At : CARSMITH PRIVATE LIMITED (HQ)

8 KAKI BUKIT AVE 4, #04-35

SINGAPORE 415875

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,367.50
Revised Amount	:S\$	650.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	650.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 40,000.00 COE / PARF Rebate :S\$ 30,274.00

Salvage Value :S\$

Margin for Repair :S\$ 9,726.00

#### Remarks

(	)	The vehicle is economical for repair
(	)	The vehicle is not economical for repair
(	Χ)	Part-by-Part repair
(	)	Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.