

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110264/EUA3Q2  
Date: 14/02/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MFL0002582\_01  
Claimant Vehicle No : SLX9056L Insured Vehicle No : SLG8803T  
Date of Loss: 11/11/2024 Nature of Claim: TP Claim No: MFL2024D0013352

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLX9056L  
Make & Model: HONDA FIT, 1.3 GF CVT (A) Engine No: L13B3878548  
Reg. Date: 16/04/2018 (Man. Year: 2018) Chassis No: GK33408929  
Colour: Grey Odometer: 61648 km  
Engine Capacity: 1317 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,225.50	3,613.52	2,611.98	41.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	2,410.00	790.00	24.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,425.50	6,023.52	3,401.98	36.09
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	9,425.50	4,800.00	4,625.50	49.07
+ GST 9.00/9.00% (S\$)	848.30	432.00	416.30	49.07
Nett Amount (S\$)	10,273.80	5,232.00	5,041.80	49.07
+ Car Rental (9.0 x S\$100.00/day + 9.00% GST) (S\$)		981.00		
Nett Liability (S\$)		6,213.00		

INSPECTION

Date of Assignment: 14/11/2024  
Date Inspected: 14/11/2024 Inspected At: Dickson Auto Care Centre Pte Ltd (HQ)  
29 Ubi Road 4, Dickson Auto Centre  
Singapore 408619  
Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE

Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Dec 2024)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX9056L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	851.80 F	*851.80 FL
2	1		*TAILGATE LOCK	Not Necessary	157.20 F	*- FL
3	1		*TAILGATE BADGE (FIT)	Necessary	37.80 F	*37.80 FL
4	1		*TAILGATE BADGE (LOGO)	Not Necessary	22.50 F	*- FL
5	1		*WINDSCREEN MOULDING REAR	Necessary	115.30 F	*115.30 FL
6	1		*REAR PANEL	Dented	397.40 F	*397.40 FL
7	1		*BUMPER REAR	Dented	529.80 F	*529.80 FL
8	10		*BUMPER CLIPS	Necessary	42.00 F	*30.00 FL
9	1		*BUMPER BRACKET REAR LH	Broken	27.50 F	*27.50 FL
10	1		*BUMPER BRACKET REAR RH	Broken	27.50 F	*27.50 FL
11	1		*BUMPER MOULDING REAR LH	Not Necessary	38.50 F	*- FL
12	1		*BUMPER MOULDING REAR RH	Cut	38.50 F	*38.50 FL
13	1		*EXHAUST SILENCER REAR	Not Necessary	498.50 F	*- FL
14	1		*BUMPER MOULDING REAR CENTRE	Cut	69.70 F	*69.70 FL
15	1		*TAILGATE COVER BOARD	Not Necessary	125.70 F	*- FL
16	10		*COVER BOARD CLIPS	Not Necessary	42.00 F	*- FL
17	1		*REAR PANEL INNER TRIM	Crushed	85.90 F	*85.90 FL
18	1		*CARPET BOOT FLOOR	Not Necessary	330.80 F	*- FL
19	1		*BOOT FLOOR	Dented	1,033.70 F	*1,033.70 FL
20	1		*TAILAMP OUTER LH	Cut	351.20 F	*351.20 FL
21	1		*TAILAMP OUTER RH	Cut	351.20 F	*351.20 FL
22	1		*TAILAMP INNER LH	Not Necessary	160.70 F	*- FL
23	1		*TAILAMP INNER RH	Not Necessary	160.70 F	*- FL
24	2		*SENSOR BRACKET REAR	Not Necessary	100.00 F	*- FL
25	1		*SENSOR REAR LH	Shorted	67.50 F	*67.50 FL
26	1		*SENSOR REAR RH	Shorted	67.50 F	*67.50 FL
27	1		*WINDSCREEN SEALANT	Necessary	100.00 F	*40.00 FL
28	1		*BUZZER	Broken	81.60 F	*81.60 FL
29	1		*CARGO BOX (SPARE TYRE FOAM)	Deformed	220.70 F	*220.70 FL
30	1		*TAILGATE WEATHERSTRIP	Torn	92.30 F	*92.30 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,225.50	4,516.90
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	903.38
Total Parts (\$\$)	6,225.50	3,613.52

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REPLACE TAILGATE TAILAMPS BUMPER REAR PANEL ,BOOT FLOOR ,EXHAUST SILENCER REAR & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	New	1,400.00	1,200.00
2	TO SPRAY TAILGATE BUMPER REAR REAR PANEL & BOOT FLOOR	New	1,100.00	1,000.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	30.00
4	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	150.00	0.00
5	TO CARRY OUT BODY CAVITY PRESERVATION	New	100.00	30.00
6	TO REMOVE & REFIX WINDSCREEN REAR	New	150.00	120.00
7	TO TRANSFER SENSORS REAR	New	100.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,200.00</b>	<b>2,410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >