

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110270/ENP3E2**Date:** 12/03/2025REFERENCE

Handling Insurer: ECICS Limited Policy No:

Claimant Vehicle No : SBS3611T **Insured Vehicle No :** GBH6202D

Date of Loss: 30/10/2024 Nature of Claim: TP Claim No: DMCV2400239H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBS3611T**

Make & Model: VOLVO B9TL, 9.4 D (A) Engine No: D9190591

Reg. Date: 12/07/2013 (Man. Year: 2013) Chassis No: YV3S4P928DA161708

Colour: Multi-colour Odometer: 0 km

Engine Capacity: 9365 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,068.34	1,516.25	3,552.09	70.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,736.00	2,036.00	700.00	25.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,804.34	3,552.25	4,252.09	54.48
Approved Total (Overridden) (S\$)		3,250.00		
Nett Amount (S\$)	7,804.34	3,250.00	4,554.34	58.36

INSPECTION

Date of Assignment: 13/11/2024

Date Inspected: 13/11/2024 Inspected At: Strides Premier Automotive Services Pte. Ltd.
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Mar 2025)	
Parts:	N/A	VOLVO B9TL 9.4 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SBS3611T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S CORNER BUMPER	Broken	974.78 F	*974.78 FL
2	1		*N/S CORNER DEFLECTOR	Broken	328.33 F	*328.33 FL
3	1		*FRT N/S LIGHT BEZEL	Missing	298.28 F	*298.28 FL
4	1		*STICKER SMRT	Necessary	75.00 FS	*75.00 FS
5	1		*DOME, FRONT:LOWER, CLASS 2, FOR VOLVO B9TL	Repair	3,391.95 F	*- FL
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (S\$)	5,068.34 1,676.39
					- List Item Discount on L Items 0.00/10.00% (S\$)	0.00 160.14
					Total Parts (S\$)	5,068.34 1,516.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHER DAMAGED AFFECTED AREAS	New	2,120.00	1,590.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	616.00	446.00
Gross Labour Cost (\$\$)			2,736.00	2,036.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >