



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLJ 9373U

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	DENTED/CRACKED	\$1,862.00	\$1,462.70
1	REAR BUMPER DIFFUSER	DENTED/CUT	\$1,015.00	\$755.20
1	REAR BUMPER TOWING COVER	SERVICEABLE	\$95.80	\$0.00
1	REAR BUMPER INNER BRACKET	CRACKED	\$562.50	\$272.00
1	REAR BUMPER LH LOWER TAIL LAMP BRACKET	SERVICEABLE	\$289.10	\$0.00
1	REAR BUMPER RH LOWER TAIL LAMP BRACKET	SERVICEABLE	\$289.10	\$0.00
2	REAR BUMPER SIDE RETAINER @\$185.20	SERVICEABLE	\$370.40	\$0.00
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	\$211.60	\$0.00
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	\$211.60	\$0.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$1,643.20	\$0.00
1	REAR END PANEL TOP GANISH	MTG CRACKED	\$364.30	\$325.10
1	REAR REINFORCEMENT	TO REPAIR SEE LABOUR	\$853.10	\$0.00
1	REAR TAIL GATE	BENT	\$2,361.40	\$1,723.90
1	REAR TAIL GATE EMBLEM (TOURAN)	NECESSARY	\$175.60	\$126.15
1	REAR TAILGATE EMBLEM (280 TSI)	NECESSARY	\$185.30	\$136.00
1	REAR TAIL GATE INNER LOCK	DENTED	\$632.50	\$133.00
1	REAR TAIL GATE INNER TRIM BOARD	MTG CRACKED	\$833.90	\$833.90
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$576.80)
			\$11,956.40	\$5,191.15

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
2	PARKING SENSOR @\$380.00 (SN)	DENTED (1PC ONLY)	\$760.00	\$200.00
6	REAR BUMPER CLIP @\$12.00 (SN)	NECESSARY	\$72.00	\$50.00
6	REAR BUMPER DIFFUSER CLIP @\$12.00 (SN)	NECESSARY	\$72.00	\$40.00
10	REAR TAIL GATE INNER TRIM CLIP @\$12.00 (SN)	NOT NECESSARY	\$120.00	\$0.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	\$80.00	\$40.00
1	PANEL SEALANT (SN)	NOT NECESSARY	\$60.00	\$0.00
1	NUMBER PLATE (SN)	SERVICEABLE	\$30.00	\$0.00
1	NUMBER PLATE COVER (SN)	SERVICEABLE	\$20.00	\$0.00
			\$1,214.00	\$330.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND REAR REINFORCEMENT	NOT NECESSARY	\$1,000.00	\$500.00
	TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA		\$600.00	\$400.00
	TO SUPPLY DIAGNOSTIC & RESET FAULT CODE TO FACILITATE THE REPAIR		\$250.00	\$0.00
	TO SUPPLY LABOUR TO DISMANTLE & REFIX INNER UPHOLSTER		\$200.00	\$60.00
	TO SUPPLY LABOUR TO DISMANTLE & REFIX REAR WINDSCREEN		\$250.00	\$120.00
	TO SUPPLY LABOUR TO REWIRE ACCIDENT AFFECT AREA		\$150.00	\$20.00
			\$2,450.00	\$1,100.00
GRAND TOTAL			\$15,620.40	\$6,621.15
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				\$5,300.00
Report Ref No: CS/AGI24110272/Knp3e2				

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.