



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2502253

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN: JASON TEA

INV Date 14/04/2025
Reference CD/FCI24110278/Rua3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMZ 666M
Insured Veh. SHA 9227D
Claim No. D24009874MFCT/CTPL/TPD 2
Policy No. D-24101860MFCT
Accident Date 08/11/2024
Inspection Date 12/11/2024

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (9%)	45.00
Grand Total	545.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN:JASON TEA		Ref: CD/FCI24110278/Rua3q2(N) Date: 14/04/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9227D	Veh. Inspected	SMZ 666M
Policy No.	D-24101860MFCT	Coverage (\$)	0.00
Claim No.	D24009874MFCT/CTPL/TPD 2	Excess (\$)	0.00
Assign From	JASON TEA	Assign Date	12/11/2024
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. M5 SALOON	c.c	4395
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WBSJF02090GA03336	Colour	BLACK
Odometer	65184 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	285/35Z R20	PIRELLI	6 mm
L/H Front Tyre	285/35Z R20	PIRELLI	6 mm
R/H Rear Tyre	285/35Z R20	PIRELLI	6 mm
L/H Rear Tyre	285/35Z R20	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/11/2024	Inspection Date	12/11/2024
Survey held at	EUROKARS AUTO PTE LTD 11 KUNG CHONG ROAD (S) 159147		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMZ 666M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	1,731.95	1,731.95
1	FLAP ,TOWING	NOT NECESSARY	69.00	-
1	REAR CENTER SUPPORT	SERVICEABLE	158.05	-
1	LOWER BUMPER COVER	SCRATCHED	428.85	428.85
1	GUIDE CENTER	SERVICEABLE	227.85	-
1	GUIDE ,REAR LH	SERVICEABLE	265.80	-
1	GUIDE ,REAR RH	SERVICEABLE	244.10	-
6	EXPANDING RIVET	NECESSARY	7.20	7.20
2	EXPANDING NUT	NECESSARY	1.10	1.10
2	PLUG-IN NUT	NECESSARY	3.00	3.00
1	CENTER LOWER SPOILER	DEFORMED	359.60	359.60
1	REAR REINFORCEMENT	SERVICEABLE	974.75	-
2	SEAL	NOT NECESSARY	9.70	-
2	REVERSE SENSOR	SERVICEABLE	808.50	-
6	SENSOR SEAL	NECESSARY	33.90	33.90
1	REFLECTOR LH	NOT NECESSARY	45.70	-
1	REFLECTOR RH	SERVICEABLE	45.70	-
2	TAILPIPE TIP	CUT	469.70	469.70
1	REAR MUFFLER	SERVICEABLE	4,134.60	-
1	CLAMPING BUSH	SERVICEABLE	152.10	-
			10,171.15	3,035.30
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
<u>LABOUR</u>				
	TO REMOVE /REPLACE REAR BUMPER ,REAR REINFORCEMENT AND ALL RELATED DAMAGED BODY PARTS .TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT .		2,125.00	850.00
	TO RESPRAY REAR BUMPER .		1,550.00	1,000.00
	TO REMOVE & REPLACE THE REAR EXHAUST ASSY .	NOT NECESSARY	850.00	-

Report Ref No. CD/FCI24110278/Rua3q2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER THE REVERSE SENSORS.		500.00	250.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		500.00	500.00
			5,775.00	2,750.00
	GRAND TOTAL		15,996.15	5,805.30

RECOMMENDED COST OF REPAIRS				5,805.30
------------------------------------	--	--	--	-----------------

Report Ref No. CD/FCI24110278/Rua3q2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 13)

PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M



PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SMZ 666M

