

Name & Address:

Motor Claims Department
 FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Vehicle No:

SMZ666M

Date:

11-Nov-24

Brand & Model:

BMW M5

Franchise:

BMW

Chassis/VIN No:

WBSJF02090GA03336

Contact Person (Eurokars):

HUI WEN

WIP#:

30048

Contact No (Eurokars):

6331 0680

Email/Fax No:

Contact No:

Type of Claim:

YEAR MODEL:

THIRD PARTY

09/10/2018

PARTS / MATERIAL CHARGES							MARK = Survey Marking [Key "A" if item is approved]
NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE	
1	REAR BUMPER <i>de</i>	51 12 8073725	1		-	\$ / 1,731.95	
2	FLAP, TOWING <i>XN?</i>	51 12 8073380	1		-	\$ 69.00	
3	REAR CENTER SUPPORT <i>? xsvl</i>	51 12 8065846	1		-	\$ 158.05	
4	LOWER BUMPER COVER <i>Report SCR /</i>	51 12 8073379	1		-	\$ / 428.85	
5	GUIDE, CENTER <i>? xsvl</i>	51 12 8067762	1		-	\$ 227.85	
6	GUIDE, REAR LH <i>? xsvl</i>	51 12 8066721	1		-	\$ 265.80	
7	GUIDE, REAR RH <i>? xsvl</i>	51 12 8066722	1		-	\$ 244.10	
8	EXPANDING RIVET <i>no</i>	51 47 1911992	6		-	\$ / 7.20	
9	EXPANDING NUT <i>no</i>	63 12 1374075	2		-	\$ / 1.10	
10	PLUG-IN NUT <i>no</i>	51 41 6989691	2		-	\$ / 3.00	
11	CENTER LOWER SPOILER <i>de</i>	51 12 8069482	1		-	\$ / 359.60	
12	REAR REINFORCEMENT <i>? xsvl</i>	51 12 7387334	1		-	\$ 974.75	
13	SEAL <i>? XN?</i>	51 12 5A7CEA6	2		-	\$ 9.70	
14	REVERSE SENSOR <i>? xsvl</i>	66 20 2409650	2		-	\$ 808.50	
15	SENSOR SEAL <i>no</i>	66 20 9283203	6		-	\$ / 33.90	
16	REFLECTOR, LH <i>? XN?</i>	63 14 7857005	1		-	\$ 45.70	
17	REFLECTOR, RH <i>? xsvl</i>	63 14 7857006	1		-	\$ 45.70	
18	TAILPIPE TIP <i>and</i>	18 10 7854029	2		-	\$ / 469.70	
19	REAR MUFFLER <i>? xsvl</i>	18 30 7883599	1		-	\$ 4,134.60	
20	CLAMPING BUSH <i>? xsvl</i>	18 30 7560815	2		-	\$ 152.10	
21						\$ -	

Sub-Total (Parts Price) \$ - \$ 10,171.15

LABOUR / SERVICES CHARGES			
NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE REAR BUMPER, REAR REINFORCEMENT AND ALL RELATED DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	<i>850</i>	\$ 2,128.00
2	TO RESPRAY REAR BUMPER.	<i>low</i>	\$ 1,550.00
3	TO REMOVE & REPLACE THE REAR EXHAUST ASSY.	<i>nett XN?</i>	850.00

4	TO TRANSFER THE REVERSE SENSORS.	nett	\$ 250 500.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150 250.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ / 500.00
7	SUNDRIES.	nett	\$ 20 50.00

Survey Date & Time: 12/11/24	Repair Days: 3 days	Excess:
---------------------------------	------------------------	---------

Surveyor Remarks:

*Resur
Hy 9w/68
Res by paint*

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	\$	-	\$	5,825.00
		REVISED		PRICE
Parts Price	\$	-	\$	10,171.15
Labour Price	\$	-	\$	5,825.00
Total (Initial Estimate)	\$	-	\$	15,996.15
Supp 1	\$	-	\$	-
Supp 2	\$	-	\$	-
Supp 3	\$	-	\$	-
Total (Before Excess)	\$	-	\$	15,996.15
Less Excess	\$	-	\$	-
TOTAL (After Excess)	\$	-	\$	15,996.15
GST	9%	\$	-	\$ 1,439.65
GRAND TOTAL	\$	-	\$	17,435.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: