

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
6 Raffles Quay, #22-00
Singapore 048580

Our File No: CS/III24060272/UVH3M4
Date: 11/07/2024

REFERENCE

Insured/Claimant: Ang See Wang (Hong Siyuan) Policy No: D22MPC0007781
Date of Loss: 24/06/2024 Nature of Claim: OD Claim No: MPC2024D0007558

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCK8838D
Make & Model: TOYOTA COROLLA ALTIS, 1.6 L CVT (A) Engine No: 1ZRX528526
Reg. Date: 10/09/2015 (Man. Year: 2015) Chassis No: MR053REH104538097
Colour: Silver Odometer: 236976 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$26,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,293.22	2,380.05	913.17	27.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	1,480.00	1,100.00	42.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,873.22	3,860.05	2,013.17	34.28
Approved Total (Overridden) (S\$)		3,050.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	5,273.22	2,450.00	2,823.22	53.54

INSPECTION

Date of Assignment: 26/06/2024
Date Inspected: 28/06/2024 Inspected At: Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jul 2024)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 L CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCK8838D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID O/S REFLECTOR	Cracked	391.70 FL	*391.70 FL
2	1		*BOOT LID LOCK	Serviceable	432.50 FL	*- FL
3	1		*BOOT LID COROLLA ALTIS EMBLEM	Necessary	93.80 FL	*93.80 FL
4	1		*BOOT LID WEATHERSTRIP	Twisted	190.10 FL	*190.10 FL
5	1		*BOOT LID LOCK STRICKER	Not Necessary	29.20 FL	*- FL
6	1		*REAR BUMPER	Deformed	620.60 FL	*620.60 FL
7	10		*REAR BUMPER CLIPS	Necessary	57.00 FL	*57.00 FL
8	2		*REAR BUMPER O/S & N/S TOP RETAINER	Not Necessary	131.20 FL	*- FL
9	2		*REAR BUMPER O/S & N/S SIDE RETAINER	Not Necessary	238.60 FL	*- FL
10	1		*REAR BUMPER REINFORCEMENT	Dented	432.50 FL	*432.50 FL
11	2		*REAR BUMPER REINFORCEMENT O/S & N/S STAY	Not Necessary	172.40 FL	*- FL
12	1		*SET REAR BUMPER REVERSE SENSOR (ORIGINAL)	Cracked	398.40 FL	*398.40 FL
13	1		*SET REAR BUMPER REVERSE SENSOR HOLDER	Not Necessary	109.80 FL	*- FL
14	1		*REAR END PANEL	Dented	727.70 FL	*727.70 FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	261.60 FL	*261.60 FL
16	6		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	37.20 FL	*- FL
17	1		*REAR NUMBER PLATE & FRAME	Serviceable	50.00 FS	*- FS
					Sub Total (S\$)	4,374.30 3,173.40
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,081.08 793.35
					Total Parts (S\$)	3,293.22 2,380.05

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	60.00	20.00
2	TO REMOVE & REFIX CARPET, FLOOR BOARD COVER, FLOOR MAT, GARNISH, SPARE TYRE, TOOL SET & NECESSARY PARTS	New	120.00	60.00
3	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT REAR FLOOR BOARD PANEL, REAR END PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	1,100.00	600.00
4	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,300.00	800.00
Gross Labour Cost (\$\$)			2,580.00	1,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >