



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 4559J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	FORK INNER TUBES	SERVICEABLE	640.00	-
2	FORK OUTER TUBES	SERVICEABLE	660.00	-
1	FORK UNDER BRACKET	NOT NECESSARY	285.00	-
1	FRONT RIM	NOT NECESSARY	580.00	-
1	FRONT FENDER	CUT	220.00	120.00
2	FRONT SIGNAL	N/S CRACKED	200.00	60.00
1	METER ASSY	NOT NECESSARY	620.00	-
2	SIDE MIRROR - R/L	SERVICEABLE	140.00	-
1	HEAD LAMP	NOT NECESSARY	480.00	-
1	LAMPSTAY	NOT NECESSARY	320.00	-
1	HANDLE BAR	BENT	280.00	280.00
1	HANDLE BAR BALANCER	CUT	90.00	50.00
1	SET HAND GRIP	NOT NECESSARY	80.00	-
1	CLUTCH LEVER	CUT	115.00	115.00
1	FUEL TANK	DENTED	620.00	620.00
2	FRONT FOOTREST	NOT NECESSARY	145.00	-
2	FRONT FOOTREST BRACKETS	NOT NECESSARY	380.00	-
1	GEAR PEDAL	CUT	135.00	110.00
2	REAR FOOTREST	NOT FITTED	155.00	-
2	REAR SIGNALS	NOT NECESSARY	200.00	-
1	REAR FENDER	CUT	280.00	185.00
1	REAR LAMP	NOT NECESSARY	420.00	-
1	SWING ARM	NOT NECESSARY	650.00	-
1	SWING ARM SHAFT	NOT NECESSARY	145.00	-
1	REAR RIM	NOT NECESSARY	680.00	-
1	REAR RIM SHAFT	NOT NECESSARY	125.00	-
1	SIDE COVER N/S	CUT	880.00	250.00
1	EXHAUST ASSY	NOT NECESSARY	750.00	-
1	EXHAUST PROTECTOR (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	125.00	-

Report Ref No. CS/INC24110286/Uvh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,040.00	-179.00
			9,360.00	1,611.00
	<u>SPECIAL NETT ITEMS</u>			
1	SET NUMBER PLATE (SN)	NOT NECESSARY	28.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	95.00	-
1	REAR BOX (SN)	CUT	480.00	280.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	180.00	-
			869.00	280.00
	<u>LABOUR</u>			
	TO CHECK WIRING AND RESET HEADLAMP FORCUSING.	NOT NECESSARY	80.00	-
	TO REPAIR BODY FRAME.	NOT NECESSARY	420.00	-
	TO PROVIDE LABOUR.		480.00	380.00
			980.00	380.00
GRAND TOTAL			11,209.00	2,271.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,800.00
---	--	--	-----------------

Report Ref No. CS/INC24110286/Uvh3e2(N)

TOTAL FOR SPARE PARTS: \$ 10,229.00 \$ 1,891.00

TOTAL FOR LABOUR : \$ 980.00 \$ 380.00

TOTAL REPAIR COST: \$ 11,209.00 \$ 2,271.00

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.