

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ECICS Limited  
10 Eunus Road 8, #09-04A Singapore Post Centre  
Singapore 408600

**Our File No:** CS/ICS24110289/UQP3M4**Date:** 20/08/2025REFERENCE

Insured/Claimant: CYCLE & CARRIAGE LEASING PTE LTD Policy No: MCF24B00000800  
Date of Loss: 07/11/2024 Nature of Claim: OD Claim No: DMCF2400102H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNG3785X**  
Make & Model: MERCEDES-BENZ E200, 2.0 (A) Engine No: 26492030494122  
Reg. Date: 29/07/2022 (Man. Year: 2022) Chassis No: W1K2130802B053991  
Colour: Black Odometer: 27992 km  
Engine Capacity: 1991 cc  
Market Value/New Car Price: S\$225,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 ZR18 Rear Tyre Size: 245/45 ZR18  
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	9,334.05	7,089.50	2,244.55	24.05
Miscellaneous Items	300.00	220.00	80.00	26.67
Labour	2,420.00	1,760.00	660.00	27.27
Paintwork Labour	1,120.00	900.00	220.00	19.64
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,174.05</b>	<b>9,969.50</b>	<b>3,204.55</b>	<b>24.32</b>
<b>- Excess (S\$)</b>	9.00	1,000.00	-991.00	-11,011.11
<b>(S\$)</b>	13,165.05	8,969.50	4,195.55	31.87
<b>+ GST 9.00/9.00% (S\$)</b>	1,184.85	807.26	377.59	31.87
<b>Nett Amount (S\$)</b>	<b>14,349.90</b>	<b>9,776.76</b>	<b>4,573.14</b>	<b>31.87</b>

INSPECTION

Date of Assignment: 14/11/2024 Present Location: Diplomat Parts Pte Ltd (HQ)  
DIPLMAT PARTS PTE LTD  
Date Inspected: 15/11/2024 Inspected At: 209 PANDAN GARDENS  
SINGAPORE 609339  
Estimated Period of Repair: 6.0 days

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 20 Aug 2025)
<b>Parts:</b> 143	MERCEDES-BENZ E200 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SNG3785X)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT BUMPER</b> (WCP)	Deformed	900.00 F	*900.00 F
2	1		<b>*MOUNTING RAIL LEFT</b> (WCP)	Not Necessary	25.00 F	*- F
3	1		<b>*CARRIER LEFT</b> (WCP)	Not Necessary	52.00 F	*- F
4	1		<b>*TRIM MOULDING</b> (WCP)	Not Necessary	120.00 F	*- F
5	1		<b>*LEFT TRIM MOULDING</b> (WCP)	Scratched	80.00 F	*80.00 F
6	1		<b>*FRONT LEFT FENDER</b> (WCP)	Bent	600.00 F	*600.00 F
7	1		<b>*FRONT LEFT WHEEL HOUSING</b> (WCP)	Serviceable	110.00 F	*- F
8	1		<b>*FRONT LEFT DOOR</b> (WCP)	Bent	1,370.00 F	*1,370.00 F
9	1		<b>*DAMPING</b> (WCP)	Not Necessary	70.00 F	*- F
10	1		<b>*DOOR SEAL</b> (WCP)	Necessary	175.00 F	*175.00 F
11	1		<b>*MIRROR SHELL</b> (WCP)	Not Necessary	120.00 F	*- F
12	1		<b>*OUTSIDE MIRROR LEFT</b> (WCP)	Not Necessary	850.00 F	*- F
13	1		<b>*SIGNAL LAMP</b> (WCP)	Not Necessary	118.00 F	*- F
14	1		<b>*MIRROR GLASS</b> (WCP)	Not Necessary	165.00 F	*- F
15	1		<b>*WHEEL RIM</b> (WCP)	Broken	1,200.00 F	*750.00 F
16	1		<b>*LH HEADLAMP</b> (WCP)	Cracked	1,890.00 F	*1,860.00 F
17	1		<b>*PARKING SENSOR OUTER</b> (WCP)	Distorted	115.00 F	*115.00 F
18	4		<b>*PARKING SENSOR SEAL</b> (WCP)	Necessary	6.50 F	*26.00 F
19	1		<b>*INSULATION DOOR</b> (WCP)	Necessary	-	*50.00 F
<b>Supplementary #1</b>						
20	1		<b>*LH TENSION STRUT</b> (WCP)	Bent	345.00 F	*345.00 F
21	1		<b>*CUPPED BLIND RIVET</b> 30PCS (WCP)	Necessary	174.00 F	*174.00 F

F=Franchise part.

<b>Sub Total (\$\$)</b>	<b>8,485.50</b>	<b>6,445.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	848.55	644.50
<b>Total Parts (\$\$)</b>	<b>9,334.05</b>	<b>7,089.50</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	ANTI RUST PROOFING	120.00	100.00
2	1	APPLY SELANT ON AFFETCED AREA	100.00	100.00
3	1	SUNDRIES (Necessary)	80.00	20.00
<b>Sub Total (\$\$)</b>			<b>300.00</b>	<b>220.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Paintwork Labour</b>				
1	SPRAY FRONT BONNET	New	200.00	200.00
2	SPRAY FRT BUMPER	New	200.00	200.00
3	SPRAY FRT LHS FENDER	New	200.00	200.00
4	SPRAY FRT LHS DOOR	New	200.00	200.00
5	SPRAY LH SIDE SILL	New	200.00	100.00
6	SPRAY LH OUTSIDE MIRROR	New	120.00	0.00
<b>Labour Items</b>				
7	RENEW FRT BUMPER	New	220.00	220.00
8	RENEW FRT LH FENDER	New	220.00	220.00
9	RENEW FRT LHS DOOR	New	220.00	220.00
10	RENEW FRONT LHS RIM	New	120.00	80.00
11	RENEW ACCIDENT DAMAGE PARTS	New	480.00	220.00
12	WHEELALIGNMENT	New	240.00	240.00
13	REPAIR FRT BONNET	New	220.00	110.00
14	CHECK WIRING AND ELECTRICAL	New	160.00	60.00
15	DIAGNOSIS AND WARNING LIGHT CHECK INCLUDING CKLEAR FAULT	New	280.00	250.00
16	RENEW FRT SENSOR	New	80.00	60.00
17	REMOVE AND REFIT/TRANSFER FRT LHS DOOR TRIM AND MECHANISM	New	180.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,540.00</b>	<b>2,660.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**