9/3/24, 11:06 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/AIG24060273/UMA3Q2

Date: 03/09/2024

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070174809 **Claimant Vehicle** SKT6699J Insured Vehicle No: SMX9993U

No:

Date of Loss: 23/06/2024 Nature of Claim: TP Claim No: 5546656761SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SKT6699J Reg No:

Make & Model: AUDI Q5, 2.0 TFSI QU S TRONIC (A) Engine No: DNN064830

Reg. Date: 26/05/2022 (Man. Year: 2022) Chassis No: WAUZZZF30N1082037

Colour: White Odometer: 34254 km

Engine Capacity: 1984 cc Market Value/New Car N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification: Nο

CONDITION OF TYRES

Front Tyre Size: 235/55 R18 Rear Tyre Size: 235/55 R18 Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		11,290.40	7,086.33	4,204.07	37.24
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,360.00	880.00	1,480.00	62.71
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	13,650.40	7,966.33	5,684.07	41.64
	+ GST 9.00/9.00% (S\$)	1,228.54	716.97	511.57	41.64
	Nett Amount (S\$)	14,878.94	8,683.30	6,195.64	41.64

+ Car Rental (2.0 x S\$130.00/day + 9.00% GST) (S\$) 283.40

+ Doc/Search Fee (S\$)

Nett Liability (S\$) 8,968.88

8,950.00 Global Sum Settlement (S\$)

INSPECTION

Date of Assignment: 08/07/2024

Specialists Motor Pte Ltd (HQ) Date Inspected: 08/07/2024 Inspected At:

Blk 3018A Ubi Road 1, #01-24/25/26

2.18

Singapore 408711

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY RH	Holder Cracked	6,696.00 F	*6,200.00 FL
2	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	147.00 F	*- FL
3	1		*FRONT FENDER RH	Repair	1,624.00 F	*- FL
4	1		*FRONT FENDER ARCH GARNISH RH	Not Necessary	639.00 F	*- FL
5	1		*FRONT BUMPER FASCIA	Dented / Deformed	1,602.00 F	*1,602.00 FL
6	1		*SET FRONT BUMPER CLIPS	Not Necessary	462.50 F	*- FL
7	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	48.20 F	*- FL
8	1		*FRONT BUMPER HEADLAMP NOZZLE COVER RH	Cracked	71.70 F	*71.70 FL
9 ===ra	1	part. L=ListIf	*BULKHEAD SUPPORT PANEL (NPA)	Not Necessary	0.00 F	*- FL
г-гіа	IIICIIISE	part. L-Listii	embisc.	Sub Total (S\$)	11,290.40	7,873.70
	- List Item Discount on L Items 0.00/10.00% (S\$)				0.00	787.37
				Total Parts (S\$)	11,290.40	7,086.33
			Report was unsubmitted during this	print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CUT OUT RENEW KNOCKING & WELIFNG FRONT FENDER RH ,FRONT SUPPORT PANEL ,REMOVE & INSTALL ALL DAMAGE PARTS & RE-ALIGN BODY	New	980.00	300.00
2	TUFF KOTE ON DAMAGE PARTS	New	40.00	0.00
3	SPRAY PAINTING ON DAMAGE PARTS	New	980.00	500.00
4	DIAGNOSTIC & RESET	New	300.00	60.00
5	CHECK ALL LIGHTING AFTER REPAIRS	New	60.00	20.00
	Gross Labour Cost (S\$)		2,360.00	880.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >