



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO PZ 3888J

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR CORNER PANEL	TO REPAIR SEE LABOUR	\$987.00	\$0.00
1	REAR RH SIDE COMPARTMENT DOOR WITH GRILLE COVER	WARPED	\$1,388.00	\$1,388.00
1	REAR (RH) TAIL LAMP ASSY	BROKEN	\$1,663.80	\$1,663.80
	LESS 10.00% DISCOUNT		(\$403.88)	(\$305.18)
			\$3,634.92	\$2,746.62

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO KNOCK OUT THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF REAR CORNER PANEL		\$1,800.00	\$600.00
	TO REMOVE AND REPLACE REAR TAIL LAMP AND CHECK FOR THE WIRING		\$120.00	\$20.00
	SUPPLY SPRAY PAINT MATERIAL (MULTI-COLOR) AND NECESSARY ITEMS TO RESPRAY ON THE ACCIDENT DAMAGE AREA AND OTHER AFFECTED AREA / PANEL		\$2,300.00	\$800.00
			\$4,220.00	\$1,420.00

GRAND TOTAL	\$7,854.92	\$4,166.62
--------------------	-------------------	-------------------

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	\$3,300.00
---	-------------------

Report Ref No: CS/INC24110295/Kvh3m4

TOTAL FOR SPARE PARTS: \$ 3,634.92 \$ 2,746.62
TOTAL FOR LABOUR : \$ 4,220.00 \$ 1,420.00
TOTAL REPAIR COST: \$ 7,854.92 \$ 4,166.62

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.