



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: HARMINDER		Ref: CS/FCI24110299/Kqp3e2(N) Date: 03/01/2025 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7941X	Veh. Inspected	SND 4845R
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24009695MFCT	Excess (\$)	0.00
Assign From	HARMINDER	Assign Date	14/11/2024
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 6 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	JM6GL1073M0456885	Colour	METALLIC DARK BLUE
Odometer	68450 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	CONTINENTAL	7 mm
L/H Front Tyre	225/55 R17	CONTINENTAL	7 mm
R/H Rear Tyre	225/55 R17	CONTINENTAL	7 mm
L/H Rear Tyre	225/55 R17	CONTINENTAL	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/11/2024	Inspection Date	20/11/2024
Survey held at	S & H MOTOR PTE LTD 160 SIN MING DRIVE #07-02 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	