



T & C AUTOMOBILE ASSESSORS

Co.Reg.53256293C

Address : 117 BUKIT MERAH VIEW #12-173 SINGAPORE 151117
HP: 97667875 Email: tcautomobileassessors@yahoo.com.sg

OFFICIAL RECEIPT

No **231110**

Date 17/11/23

RECEIVED From

Low Ee Ching

the sum of Dollars

One thousand one hundred and forty only

being payment of

TC6 2023 10/07.

SGD

11207.

☐ Cash


☐ Cheque

☒ NETS

Chun



Authorised's Signature



T C AUTOMOBILE ASSESSORS

TAX INVOICE

KANG AUTO ENGINEERING PTE LTD
Blk 160 Sin Ming Drive
#02-16 Singapore 575722
On Behalf Of
LOW EE CHING

INV NO. : TC6202310107

DATE : 17 November 2023

DESCRIPTION

AMOUNT S\$

Survey Fees
(Including photographs and transport charges)

1,120.00

1,120.00

VEHICLE NO. : SMQ4563Y
JOB REFERENCE NO. : TC/6/2023/10107
ACCIDENT DATE : 15 October 2023
SURVEY DATE : 18 October 2023

T&C AUTOMOBILE ASSESSORS

Chun



117 BUKIT MERAH VIEW #12-173 SINGAPORE 151117
HP : 97667875 Email : tcautomobileassessors@yahoo.com.sg
Co.Reg.53256293C



T C AUTOMOBILE ASSESSORS

LOW EE CHING
C/O KANG AUTO ENGINEERING PTE LTD
Blk 160 Sin Ming Drive
#02-16 Singapore 575722

REF : TC/6/2023/10107

Date : 17 November 2023

VEHICLE SURVEY REPORT

REFERENCE

Request By : Workshop , On Behalf Of Owner
Date Of Request : 17 October 2023
Date Of Accident : 15 October 2023
Date Of Inspection : 18 October 2023
Inspected At : KANG AUTO ENGINEERING PTE LTD
Blk 160 Sin Ming Drive
#02-16 Singapore 575722

PARTICULARS OF VEHICLE

Vehicle Reg. No. : SMQ4563Y	Make & Model : MERCEDES BENZ GLC200 (R18 LED)
Year Make : 2017	Colour : White
Engine No. : 27492031228207	Chassis No. : WDC2539422F344486
Engine Capacity : 1991 cc	

CONDITION OF VEHICLE AND TYRES

General condition : Good	Mileage : 177,141 KM
Brakes : Serviceable	Modification : None
Steering : Serviceable	Handbrake : Serviceable

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (mm)</u>
Front RHS	MICHELIN	235/60R18	8
Front LHS	MICHELIN	235/60R18	8
Rear RHS	MICHELIN	235/60R18	8
Rear LHS	MICHELIN	235/60R18	8

DESCRIPTION OF DAMAGES

The vehicle sustained damages at the REAR portion.
(For information of damages , please refer to Parts / Labour / Photographs attached)

INSTRUCTION

This survey was conducted entirely on a "WITHOUT PREJUDICE" basis , and we have not authorised any repair .



T C AUTOMOBILE ASSESSORS

Annex A

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No : SMQ4563Y

Report No : TC/6/2023/10107

PARTS

<u>S/NO</u>	<u>QTY</u>	<u>DESCRIPTION</u>	<u>CONDITION / REMARKS</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
1	1	Tailgate	Dent	3,685.20	3,685.20 x R
2	1	Tailgate Logo	Necessary	183.00	183.00 90 /
3	1	Tailgate Emblem - Glc250	Necessary	208.35	208.35 100 /
4	1	Tailgate Lock	Bent	876.90	876.90 x nn
5	1	Tailgate Weatherstrip	Deformed	389.70	389.70 x nn
6	1	Rear Bumper	Deformed	2,768.85	2,768.85 x R
7	1	Rear Bumper Lower Trim (Black)	Deformed	2,188.35	2,188.35 748 /
8	1	Rear Bumper Lower Chrome	Torn	1,250.40	1,250.40 1025 /
9	1	Rear Bumper Reflector Lh	Reuse	238.35	0.00
10	1	Rear Bumper Reflector Rh	Reuse	238.35	0.00
11	1	Rear Bumper Reinforcement	Dent	1,139.70	1,139.70 x nn
12	1	Rear Bumper Side Guide Lh	Torn	261.75	261.75 x nn
13	1	Rear Bumper Side Guide Rh	Torn	261.75	261.75 x nn
14	1	Rear Bumper Guide Lh	Torn	186.75	186.75 x nn
15	1	Rear Bumper Guide Rh	Torn	186.75	186.75 x nn
16	1	Rear End Panel	Repair	2,285.55	0.00
17	4 1	Parking Sensor	Malfunction	1,260.00	1,260.00 260 /
18	1	Exhaust End Dip Lh	Glazed	428.85	428.85 x nn
19	1	Exhaust End Dip Rh	Glazed	428.85	428.85 x nn
20	1	Foot Sensor	Malfunction	688.35	688.35 x nn
				19,155.75	16,393.50
Less : Discount 10%				-1,915.58	-1,639.35
Total :				17,240.18	14,754.15



T C AUTOMOBILE ASSESSORS

Annex A

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No : SMQ4563Y

Report No : TC/6/2023/10107

MISCELLANEOUS ITEMS

<u>S/NO</u>	<u>QTY</u>	<u>DESCRIPTION</u>	<u>CONDITION / REMARKS</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>	
1	1	Glass Sealant	Necessary	40.00	40.00	x nn
Total :				40.00	40.00	



T C AUTOMOBILE ASSESSORS

Annex B


ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No : SMQ4563Y

Report No : TC/6/2023/10107

PANEL & MECHANICAL LABOUR

<u>S/NO</u>	<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>	
1	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	1,000.00	500.00	350
2	To check wirings and lightings.	60.00	20.00	/
3	To remove & install reverse sensor.	60.00	20.00	/
4	To remove & refix tailgate fittings to facilitate repair.	120.00	100.00	x
5	To remove & refix rear upholstery, garnish and attachment.	120.00	0.00	
6	To supply sealant and to seal off all weld spot seam and gaps.	100.00	0.00	
7	To spray anti-rust coating.	120.00	0.00	
8	To remove and refix rear windscreen glass.	150.00	150.00	x
Total :		<u>1,730.00</u>	<u>790.00</u>	



T C AUTOMOBILE ASSESSORS

Annex B

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No : SMQ4563Y

Report No : TC/6/2023/10107

PAINT

Code : Two Coat Metallic

LABOUR COST - PAINT

<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
To applies body filler , sanding , applies primer coat , spray painting and clearcoat. And polish the affected portions.	800.00	500.00 400
Total :	800.00	500.00

MATERIAL COST - PAINT

<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
To supplies polyurethane paint, clear coat lacquer, primer, masking tape, cleaning solvent, 1200- and 2000-grit sandpaper, filler, and paint thinner.	250.00	130.00 80
Total :	250.00	130.00

FINAL CALCULATION

<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
Parts	17,240.18	14,754.15
Miscellaneous items	40.00	40.00
Panel & Mechanical Labour	1,730.00	790.00
Paint Labour	800.00	500.00
Paint Material	250.00	130.00
Total Repair Cost :	20,060.18	16,214.15

Remarks

The repairer has agreed to undertake the repair of **S\$ 16,214.15**
And with a repair period of **5** working days .

Surveyed by:

Chin



CHIN ZOEN LI