

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SJC 2052C

	REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	REAR BOOTLID	DENTED	\$1,296.90	\$1,296.90			
1	REAR BOOTLID OUTER GARNISH	SERVICEABLE	\$399.90	\$0.00			
2	REAR BOOTLID NUMBER PLATE LAMP	SERVICEABLE	\$220.00	\$0.00			
1	REAR BOOTLID LOGO	NECESSARY	\$95.00	\$95.00			
1	REAR BOOTLID 'AXIO' EMBLEM	NECESSARY	\$98.00	\$98.00			
1	REAR BOOTLID 'X' EMBLEM	NECESSARY	\$88.00	\$88.00			
1	REAR BOOTLID LOCK	NOT NECESSARY	\$385.00	\$0.00			
1	REAR BOOTLID LOCK STRIKER	SERVICEABLE	\$98.00	\$0.00			
1	REAR BOOTLID TRIM	NOT NECESSARY	\$596.00	\$0.00			
2	REAR BOOTLID HINGES	NOT NECESSARY	\$320.00	\$0.00			
1	REAR BOOTLID WEATHERSTRIP	DEFORMED	\$388.00	\$388.00			
1	REAR RHS FENDER	TO REPAIR SEE LABOUR	\$1,554.00	\$0.00			
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	\$420.00	\$0.00			
1	REAR RHS TAILLAMP	CRACKED	\$920.00	\$920.00			
1	REAR RHS TAILLAMP PANEL	TO REPAIR SEE LABOUR	\$388.00	\$0.00			
1	REAR RHS TAILLAMP LOWER BRACKET	CRACKED	\$165.00	\$165.00			
1	REAR BUMPER	CRACKED	\$1,088.00	\$590.00			
2	REAR BUMPER RETAINER	NECESSARY	\$280.00	\$220.00			
2	REAR BUMPER BRACKET	NOT NECESSARY	\$320.00	\$0.00			
1	REAR RHS BUMPER END SHIELD	NOT NECESSARY	\$165.00	\$0.00			
1	REAR END PANEL	DENTED	\$988.00	\$689.00			
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	\$340.00	\$0.00			
1	REAR RHS FENDER INNER TRIMBOARD	NOT NECESSARY	\$699.00	\$0.00			
1	REAR SPARE TYRE TOP BOARD	NOT NECESSARY	\$550.00	\$0.00			
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	\$1,408.00	\$0.00			
1	REAR EXHAUST GASKET	NOT NECESSARY	\$50.00	\$0.00			
1	REAR EXHAUST SILENCER	NOT NECESSARY	\$1,380.00	\$0.00			
1	REAR EXHAUST HEAT SHIELD	SERVICEABLE	\$440.00	\$0.00			
2	REAR EXHAUST MOUNTING	NOT NECESSARY	\$200.00	\$0.00			
	LESS 25.00% DISCOUNT		(\$3,834.95)	(\$1,137.48)			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

\$11,504.85

\$2,500.00

\$2,500.00

\$900.00

\$1,000.00

\$3,412.42

Special Nett						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REVERSE CAMERA (SN)	SERVICEABLE	\$500.00	\$0.00		
1	REVERSE SENSOR (SN)	SHORTED	\$400.00	\$200.00		
1	SET REAR BUMPER CLIP (SN)	NECESSARY	\$100.00	\$30.00		
1	SET REAR BOOTLID TRIM CLIP (SN)	NOT NECESSARY	\$100.00	\$0.00		
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	\$100.00	\$0.00		
1	SET FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	\$100.00	\$0.00		
1	TAILLAMP CLIP (SN)	NOT NECESSARY	\$100.00	\$0.00		
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	\$200.00	\$0.00		
			\$1,600.00	\$230.00		
Labour						
	Labo	ur				
	Description of Parts	ur Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
		•	Workshop Estimate (\$) \$100.00	Our Adjusted (\$) \$30.00		
	Description of Parts	•		, ,,,		
	Description of Parts TO CHECK WIRING AND LIGHTING	•	\$100.00	\$30.00		
	Description of Parts TO CHECK WIRING AND LIGHTING TO REMOVE AND REPLACE REAR REVERSE SENSOR	•	\$100.00 \$180.00	\$30.00 \$30.00		
	Description of Parts TO CHECK WIRING AND LIGHTING TO REMOVE AND REPLACE REAR REVERSE SENSOR TO REMOVE AND REFIX REAR REVERSE CAMERA	Condition	\$100.00 \$180.00 \$200.00	\$30.00 \$30.00 \$50.00		
	Description of Parts TO CHECK WIRING AND LIGHTING TO REMOVE AND REPLACE REAR REVERSE SENSOR TO REMOVE AND REFIX REAR REVERSE CAMERA TO CONDUCT WATER SEEPAGE TEST	Condition	\$100.00 \$180.00 \$200.00 \$120.00	\$30.00 \$30.00 \$50.00		
	Description of Parts TO CHECK WIRING AND LIGHTING TO REMOVE AND REPLACE REAR REVERSE SENSOR TO REMOVE AND REFIX REAR REVERSE CAMERA TO CONDUCT WATER SEEPAGE TEST TO TRANSFER REAR BOOTLID MECHANISM FROM OLD TO NEW	Condition NOT NECESSARY	\$100.00 \$180.00 \$200.00 \$120.00 \$240.00	\$30.00 \$30.00 \$50.00 \$0.00		
	Description of Parts TO CHECK WIRING AND LIGHTING TO REMOVE AND REPLACE REAR REVERSE SENSOR TO REMOVE AND REFIX REAR REVERSE CAMERA TO CONDUCT WATER SEEPAGE TEST TO TRANSFER REAR BOOTLID MECHANISM FROM OLD TO NEW TO REMOVE AND REPLACE REAR EXHAUST SILENCER	Condition NOT NECESSARY NOT NECESSARY	\$100.00 \$180.00 \$200.00 \$120.00 \$240.00	\$30.00 \$30.00 \$50.00 \$0.00 \$0.00		
	Description of Parts TO CHECK WIRING AND LIGHTING TO REMOVE AND REPLACE REAR REVERSE SENSOR TO REMOVE AND REFIX REAR REVERSE CAMERA TO CONDUCT WATER SEEPAGE TEST TO TRANSFER REAR BOOTLID MECHANISM FROM OLD TO NEW TO REMOVE AND REPLACE REAR EXHAUST SILENCER TO REMOVE AND REFIX REAR WINDSCREEN ASSY	Condition NOT NECESSARY NOT NECESSARY	\$100.00 \$180.00 \$200.00 \$120.00 \$240.00 \$240.00 \$300.00	\$30.00 \$30.00 \$50.00 \$0.00 \$0.00		

	\$6,980.00	\$2,140.00		
GRAND TOTAL	\$20,084.85	\$5,782.42		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$4,600.00		
Report Ref No: CS1/LPM24110303/Enh3e2				

TO PANEL BEAT AND REPLACE DAMAGED PARTS ON AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR RHS FENDER, REAR

RHS TAILLAMP PANEL AND REAR SPARE TYRE PANEL

TO PUTTY AND SPRAY PAINTING ON AFFECTED AREAS

MARKET VALUE: \$5,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$2,298.00=NETT VALUE: \$2,702.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.