

# ICON MOTOR APPRAISER PTE LTD

Motor Appraiser and Insurance Loss Adjustor  
Blk 361 Yung An Road #12-105 Singapore 610361  
Mobile: +65 9232 0012 Email: iconappraiser@gmail.com  
UEN. : 202006885Z

## INVOICE

To : WON WEE SON  
c/o : 168 Auto Services Pte Ltd  
176 Sin Ming Drive #05-14  
Sin Ming Autocare  
Singapore 575721

Date : 12 Jan 2024  
Invoice No. : 2024-00354  
Ref : 20240112/00354/168

DESCRIPTION	AMOUNT
<b>Service rendered for appraisal / inspection report :</b>	
Professional inspection fees	SGD 1,500.00
<b>Total</b>	SGD 1,500.00
Singapore dollar : ONE THOUSAND FIVE HUNDRED ONLY.	
Registration no. : SMX2643B	
Make/Model : TOYOTA SIENTA HYBRID 1.5X CVT	
Our reference : 20240112/00354/168	
<b>All payments made payee to:-</b> <b>" ICON MOTOR APPRAISER PTE LTD "</b> <b>Please note payment terms:- 30 days from invoice date</b>	



\*for ICON MOTOR APPRAISER PTE LTD

# **MOTOR APPRAISER PTE LTD**

Motor Appraiser and Insurance Loss Adjustor  
Blk 361 Yung An Road #12-105 Singapore 610361  
Mobile: +65 9232 0012 Email: iconappraiser@gmail.com  
UEN: 202006885Z

## **INSPECTION REPORT**

To : WON WEE SON

Our ref. : 20240112/00354/168

Date : 12 Jan 2024

### **REFERENCE**

Assign by : WON WEE SON  
3rd party Veh. : **WHY9818**  
Inspection on : 18 Dec 2023  
Accident on : 15 Dec 2023  
Workshop name : 168 Auto Services Pte Ltd  
Inspection at : 176 Sin Ming Drive #05-14  
Sin Ming Autocare  
Singapore 575721

### **PARTICULARS OF DAMAGED VEHICLE**

Registration no.	: SMX2643B	Odometer	: 58065 km
Make / Model	: TOYOTA SIENTA HYBRID 1.5X CVT	Chassis no.	: NHP1707173172
Regn. date	: 2021	Engine no.	: 1NZR784392
Body colour	: Brown	Engine cap.	: 1496 cc

### **PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)**

Steering	: In order	Paintwork	: Fair
Footbrake	: In order	Undercarriage	: Serviceable
Handbrake	: In order	Gen. condition	: Fair

### **TYRE CONDITION ON VEHICLE**


	Make	Size	Tread depth	Type of road wheel
Front N/S	: Yokohama	185/60R15	70%	Steel
Front O/S	: Yokohama	185/60R15	70%	Steel
Rear N/S	: Yokohama	185/60R15	70%	Steel
Rear O/S	: Yokohama	185/60R15	70%	Steel

*NOTE: Tread depth percentages represents the visually estimated remaining life of tyre treads.*

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

### POINT OF IMPACT

The damages was found on the rear portion.



### RECOMMENDATION

The estimated cost of repair submitted by the repairer 168 Auto Services Pte Ltd as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairer have agreed to undertake the repairs at our recommendation.

Our adjusted cost of repair is SGD 7,600.00 to carry out the repairs. Kindly refer to parts and labour portion for a detailed account of the cost estimates.

### REMARKS

However, for your information, under normal circumstances, the repair normally would take approximately 8 (Eight) working days to complete.

We have **NOT AUTHORISED** the repair to the damaged vehicle. The survey was conducted strictly on a "**WITHOUT PREJUDICE**" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our final report, which includes material damages photographs.

Yours faithfully,  
ICON Motor Appraiser Pte Ltd



Patrick Ng  
Motor Vehicle Appraiser

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.



# ICON MOTOR APPRAISER PTE LTD

## List items

S/N	Parts description	QTY	Condition	Repairer's Estimate	Our Recommendation	
1	Tailgate	1	Damaged	\$ 1,850.00	\$ 1,850.00	1602 /
2	Tailgate outer garnish	1	Re-use	--	--	
3	Tailgate logo	1	Necessary	\$ 75.00	\$ 75.00	/
4	Tailgate weatherstrip	1	Deformed	\$ 274.00	\$ 274.00	x nn
5	Tailgate lock	1	Jammed	\$ 385.00	\$ 385.00	/
6	Floor panel top board	1	Damaged	\$ 489.00	\$ 489.00	x nn
7	Tailgate "HYBRID" emblem	1	Necessary	\$ 76.00	\$ 76.00	/
8	Antenna buzzer	1	Damaged	\$ 269.00	\$ 269.00	153 /
9	Tailgate hinge	2	Re-use	--	--	
10	Tailgate damper	2	Re-use	--	--	
11	Tailgate windscreen moulding	1	Necessary	\$ 194.00	\$ 194.00	110 /
12	Rear bumper side cover	2	Damaged	\$ 484.00	\$ 484.00	/
13	Rear bumper side reflector	2	Damaged	\$ 354.00	\$ 354.00	x nn
14	Rear bumper cover retainer	2	Cracked	\$ 104.00	\$ 104.00	/
15	Rear bumper centre protector	1	Damaged	\$ 694.00	\$ 694.00	460 /
16	Rear bumper	1	Damaged	\$ 1,150.00	\$ 1,150.00	/
17	Rear bumper retainer	2	Damaged	\$ 152.00	\$ 152.00	/
18	Rear bumper bracket	2	Bent	\$ 136.00	\$ 136.00	x nn
19	End panel	1	Buckled	\$ 785.00	\$ 785.00	599 /
20	End panel top garnish	1	Damaged	\$ 284.00	\$ 284.00	/
Subtotal				\$ 7,755.00	\$ 7,755.00	
Discount (less 25.00%)				\$ -	\$ 1,938.75	
Total				\$ 7,755.00	\$ 5,816.25	

## Special nett items

No.	Parts description	QTY	Condition	Repairer's Estimate	Our Recommendation	
1	Tailgate windscreen inner seal	1	Necessary	\$ 100.00	\$ 80.00	30
2	Tailgate windscreen sealant	1	Necessary	\$ 100.00	\$ 80.00	40
3	Tailgate outer garnish clips	1	Necessary	\$ 40.00	\$ 30.00	x nn
4	Tailgate trimboard clips	1	Necessary	\$ 50.00	\$ 40.00	x nn
5	End panel top garnish clips	1	Necessary	\$ 50.00	\$ 40.00	20
6	End panel sealant	1	Necessary	\$ 100.00	\$ 80.00	30
7	Rear licence plate & frame	1	Damaged	\$ 60.00	\$ 50.00	x nn
8	Reverse sensor	1	Damaged	\$ 300.00	\$ 250.00	200
9	Rear bumper clips	1	Necessary	\$ 80.00	\$ 60.00	20
10	Rear bumper side cover clips	1	Necessary	\$ 60.00	\$ 40.00	20
11	Sundries	1	Necessary	\$ 60.00	\$ 50.00	30
Total				\$ 1,000.00	\$ 800.00	

Labour					
No.	Description	QTY	Repairer's Estimate	Our Recommendation	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	1	\$ 1,600.00	\$ 1,400.00	1000
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	1	\$ 80.00	\$ 60.00	30
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	1	\$ 150.00	\$ 120.00	50
4	To remove and refit rear windscreen to facilitate repair work.	1	\$ 150.00	\$ 120.00	/
5	Supply spray paint material and necessary items to affected area / panel.	1	\$ 1,400.00	\$ 1,200.00	600
6	To rust proof all affected portions after repair.	1	\$ 100.00	\$ 60.00	30
Total labour			\$ 3,480.00	\$ 2,960.00	

Estimate Grand Total	\$ 12,235.00	\$ 9,576.25
----------------------	--------------	-------------

7 days.