



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD C/O PKWA LAW PRACTICE LLC 480 LORONG 6 TOA PAYOH #16-01 HDB HUB EAST WING SINGAPORE 310480			Ref: CS/LAW24110306/Aqh3e2(N)	Date: 06/02/2025
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	GBC 2704A	Veh. Inspected	GBL 8336S
	Policy No.	SNM24D200226	Coverage (\$)	0.00
	Claim No.	CC.50331.24.CTP	Excess (\$)	0.00
	Assign From	JOEANN PHUA	Assign Date	14/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	TRH2005049120	Colour	GREEN
	Odometer	57234 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	TOYO	6 mm
	L/H Front Tyre	195 R15C	TOYO	6 mm
	R/H Rear Tyre	195 R15C	TOYO	6 mm
	L/H Rear Tyre	195 R15C	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information				
	Accident Date	10/01/2024	Inspection Date	03/01/2025
	Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	