

Vehicle Information

Claim Type	Third Party Claim	Claim Number	SNM24D200226
Vehicle No.	GBL8336S	Date of Loss	10/01/2024 11:50:00
Manufacturer	TOYOTA	Model	HIACE 2.0 DX AUTO
VIN	TRH2005049120	Odometer	23442.00 Km
Date of Inspection	12/01/2024 00:00:00	Repair Days	14.00 D
Engine No.	1TR2399256	Colour	SILVER
Estimator	XIN HUA WORKSHOP		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable)	Yes	Footbrake (Serviceable)	Yes
Handbrake (Serviceable)	Yes	Engine Modification	No

CONDITION OF TYRES

Front Tyre Size	195/15	Rear Tyre Size	195/15
Front Left Side:(mm)	5	Rear Left Side:(mm)	5
Front Right Side:(mm)	5	Rear Right Side:(mm)	5

1. Surveyor name 2. Point impact/General Description of Damages 3. Vehicle registration date
4. Engine Capacity 5. Repair Margin 6. Mandate request amount

1. Surveyed by Mr Mohd Fadhilah Bin Osman 2. The impacts were confined to the front and rear portions of the vehicle. 3. Estimated COR \$10,000.00. 4. Registration date - 26.04.2022, 1998CC

Part Information

Particulars	Condition	Qty.	Repairer's	Surveyor's
TAILGATE INNER TRIM BOARD	DEFORMED	1	0	0
TAILGATE	BUCKLED	1	0	0
TAILGATE OUTER GARNISH	GRAZED	1	0	0
TAILGATE WINDSCREEN	SMASHED	1	0	0
TAILGATE LOCK	JAMMED	1	0	0
RH TAILLAMP	CRACKED	1	0	0
REAR BUMPER	DEFORMED	1	0	0
REAR BUMPER LOWER BRACKET	TWISTED	1	0	0
REAR BUMPER SIDE HOLDER	DISLODGED	1	0	0
REAR RH FENDER	BUCKLED	1	0	0
REAR RH TAILLAMP PANEL	BUCKLED	1	0	0
REAR RH TAILLAMP LOWER GARNISH	DEFORMED	1	0	0
REAR LH TAILLAMP	CRACKED	1	0	0
REAR STEP PPANEL	TWISTED	1	0	0
REAR FLOOR PANEL	BUCKLED	1	0	0
SPARE TYRE BRACKET	TWISTED	1	0	0
SPARE TYRE BRACKET BOLT	TWISTED	1	0	0
PLYWOOD	CRACKED	1	0	0
FRONT BUMPER	DEFORMED	1	0	0
FRONT REINFORCEMENT LOWER	DISTORTED	1	0	0

FRONT REINFORCEMENT UPPER	DISTORTED	1	0	0
AIRCON CONDENSER	TWISTED	1	0	0
HEADLAMPS	CRACKED	2	0	0
FRONT GRILLE	CRACKED	1	0	0
Sub Total Parts (\$\$)			0.00	0.00
Total Parts Discount/Mark Up			%	
Total Parts (\$\$)			0.00	0.00

Miscellaneous Items

Miscellaneous Items	Repairer's	Surveyor's
No Data		

Labour Information

Labour Items	Repairer's	Surveyor's
No Data		

Cost of Claims	Repairer's	Adjuster's	Difference	Diff%
Total Parts	0.00	0.00	0.00	0.00%
Total Miscellaneous Items Cost	0.00	0.00	0.00	0.00%
Total Labour Cost	0.00	0.00	0.00	0.00%
Calculated Gross Total(\$\$)	0.00	0.00	0.00	0.00%
Less				
GST Rate 0%	0.00	0.00	0.00	0.00%
Nett Amount(\$\$)	0.00	0.00	0.00	0.00%

Remarks

☒ Other Comments

This pre-repair inspection is conducted on a "Without Prejudice" basis. Economical Repair Value \$64,336.00 (Estimated Market Value \$93,000.00 less LTA rebate \$28,664.00) Our visual inspection of the subject vehicle revealed that the damage noted is consistent with the reported accident.