

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24110308/UQP3E2**Date:** 30/04/2025REFERENCE

Insured/Claimant:	ANG EE SIN	Policy No:	MPC24A00143401	
Date of Loss:	08/11/2024	Nature of Claim:	OD	Claim No: DMPC2401538H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJP8295K		Engine No:	Z24SED037891
Make & Model:	CHEVROLET CAPTIVA, 2.4 (A)		Chassis No:	KL1CD26F18B214406
Reg. Date:	14/04/2009 (Man. Year: 2008)		Odometer:	381461 km
Colour:	White			
Engine Capacity:	2405 cc			
Market Value/New Car Price:	S\$35,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,489.25	6,063.75	2,425.50	28.57
Miscellaneous Items	160.00	50.00	110.00	68.75
Labour	1,320.00	620.00	700.00	53.03
Paintwork Labour	1,000.00	600.00	400.00	40.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,969.25	7,333.75	3,635.50	33.14
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	10,969.25	5,800.00	5,169.25	47.12
+ GST 9.00/9.00% (S\$)	987.23	522.00	465.23	47.12
Nett Amount (S\$)	11,956.48	6,322.00	5,634.48	47.12

INSPECTION

Date of Assignment:	15/11/2024	Present Location:	Automobile Integrated Management Pte Ltd (HQ)
Date Inspected:	18/11/2024	Inspected At:	Automobile Integrated Management Pte Ltd (HQ)
			3021A Ubi Road 1, #01-42
			Singapore 408715
Estimated Period of Repair:	5.0 days		

Adjuster: SHIAU CHAN**Manager:** MARCUS CHUA*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Apr 2025)
Parts:	M1-SUV	CHEVROLET CAPTIVA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP8295K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		Air-cond condenser (WCP)	Bent / Punctured	625.00 F	*625.00 F
2	1		Bonnet (WCP)	Repair	1,062.50 F	*- F
3	1		Bonnet lock (WCP)	Bent / Twisted	131.25 F	*131.25 F
4	10		Bumper clip, front (WCP)	Necessary	37.50 F	*20.00 F
5	1		Bumper fog lamp cover LH (WCP)	Deformed	15.00 F	*15.00 F
6	1		Bumper fog lamp cover RH (WCP)	Grazed	15.00 F	*15.00 F
7	1		Bumper fog lamp LH, front (WCP)	Not Necessary	131.25 F	*- F
8	1		Bumper fog lamp RH, front (WCP)	Not Necessary	131.25 F	*- F
9	1		Bumper reinforcement, front (WCP)	Bent	500.00 F	*500.00 F
10	1		Bumper, front (WCP)	Torn	687.50 F	*687.50 F
11	1		Headlamp LH (WCP)	Broken	1,200.00 F	*1,100.00 F
12	1		Headlamp RH (WCP)	Broken	1,200.00 F	*1,100.00 F
13	1		Radiator (WCP)	Serviceable	562.50 F	*- F
14	1		*Center grille (top) assy (WCP)	Cracked	500.00 F	*400.00 F
15	1		*Logo emblem (WCP)	Necessary	50.00 F	*50.00 F
16	1		*Lower grille (WCP)	Cracked	250.00 F	*250.00 F
17	1		*Front bumper lower (WCP)	Distorted	275.00 F	*275.00 F
18	1		*Front bumper lower center (WCP)	Torn	225.00 F	*225.00 F
19	1		*Support panel top garnish (WCP)	Cracked	118.75 F	*118.75 F

F=Franchise part.

Sub Total (S\$)	7,717.50	5,512.50
+ Margin on L,N Items 10.00/10.00% (S\$)	771.75	551.25
Total Parts (S\$)	8,489.25	6,063.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Air-cond gas (Normal) (NECESSARY)	60.00	20.00
2	1	Number plate, front (BENT)	40.00	30.00
3	1	Radiator coolant (NOT NECESSARY)	60.00	0.00
Sub Total (\$\$)			160.00	50.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Spraypaint	New	1,000.00	600.00
Labour Items				
2	Wiring	New	120.00	20.00
3	Panel beating	New	1,200.00	600.00
Gross Labour Cost (\$\$)			2,320.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >