

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN		Ref:	CS/INC24110318/Anh3e2(N)		
	75 BRAS BASAH R INCOME CENTRES		Date:	21/01/2025		
	ATTN: ENG HUEY	HUEY		Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBK 9061H	Veh. Inspected	d	SNA 8851L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1304325-001	Excess (\$)		0.00	
	Assign From	ENG HUEY HUEY	Assign Date		15/11/2024	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA ODYSSEY	c.c		2356	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JHMRC1890KC200364	Colour		PURPLE	
	Odometer	125388 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/55 R17	TOYO		6 mm	
	L/H Front Tyre	215/55 R17	TOYO		6 mm	
	R/H Rear Tyre	215/55 R17	TOYO		6 mm	
	L/H Rear Tyre	215/55 R17	TOYO		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
					12	
5.	General Information					
	Accident Date	14/11/2024	Inspect Date /	Time	15/11/2024 ( 03:06 PM )	
	Survey held at	y held at JL PERFECT AUTOWORK PTE LTD				
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	•					