



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: ENG HUEY HUEY

Ref: CS/INC24110320/Anh3e2(N)

Date: 06/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFF 2806B	Veh. Inspected	YR 1472Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1303937-002	Excess (\$)	0.00
Assign From	ENG HUEY HUEY	Assign Date	15/11/2024

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI CANTER	c.c	2998
Engine No.	HIDDEN	Year of Reg.	2024
Chassis No.	FEB21EA36544	Colour	WHITE
Odometer	81201 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/85 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/85 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/85 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/85 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/11/2024	Inspect Date / Time	15/11/2024 (02:16 PM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days