



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLU 2126E

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DEFORMED/TWISTED	\$710.60	\$579.90
1	FRONT BUMPER TOP SEAL	NECESSARY	\$89.90	\$89.90
1	FRONT BUMPER TOP BEAM	NOT NECESSARY	\$220.10	\$0.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	\$410.50	\$0.00
2	FRONT BUMPER SIDE RETAINERS -R/L @\$45.50	O/S BENT	\$91.00	\$10.40
2	FRONT HEADLAMPS -R/L @\$1,439.50	O/S HOLDER CRACKED	\$2,879.00	\$1,201.10
2	FRONT HEADLAMPS CHROME MOULDING -R/L @\$86.90	NOT NECESSARY	\$173.80	\$0.00
1	FRONT GRILLE BASE	CRACKED	\$211.90	\$211.90
1	FRONT GRILLE LOGO	NECESSARY	\$86.60	\$38.80
1	FRONT GRILLE CHROME MOULDING	NOT NECESSARY	\$286.90	\$0.00
2	FRONT HEADLAMP LOWER BRACKETS -R/L @\$89.60	O/S CRACKED	\$179.20	\$89.60
	<b>LESS 20.00% DISCOUNT</b>		(\$1,067.90)	(\$444.32)
			<b>\$4,271.60</b>	<b>\$1,777.28</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$60.00	\$30.00
			<b>\$60.00</b>	<b>\$30.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK FRONT ELECTRICAL WIRING		\$50.00	\$20.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		\$600.00	\$300.00
	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT		\$600.00	\$250.00
			<b>\$1,250.00</b>	<b>\$570.00</b>

<b>GRAND TOTAL</b>	<b>\$5,581.60</b>	<b>\$2,377.28</b>
--------------------	-------------------	-------------------

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>	<b>\$1,900.00</b>
---	-------------------

Report Ref No: CS/INC24110323/Uqh3m4

TOTAL FOR SPARE PARTS: \$ 4,331.60 \$ 1,807.28  
TOTAL FOR LABOUR : \$ 1,250.00 \$ 570.00  
TOTAL REPAIR COST: \$ 5,581.60 \$ 2,377.28



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## **CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.