

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBC 9484M

	Special Nett					
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	TAILLAMP O/S (SN)	BROKEN	\$150.00	\$150.00		
1	REAR HYDRAULIC LONG LIFT UP TAILGATE DAMPER O/S (SN)	DAMAGED	\$3,500.00	\$2,500.00		
1	REAR HYDRAULIC SHORT LIFT UP TAILGATE DAMPER O/S (SN)	NOT NECESSARY	\$2,500.00	\$0.00		
1	REAR HYDRAULIC LIFT UP TAILGATE DAMPER BRACKETS O/S (SN)	TO REPAIR SEE LABOUR	\$600.00	\$0.00		
1	REAR PANEL (SN)	TO REPAIR SEE LABOUR	\$680.00	\$0.00		
			\$7,430.00	\$2,650.00		

Labour			
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
TO CHECK WIRING		\$50.00	\$20.00
TO SPRAY RUST PROOFING	NOT NECESSARY	\$80.00	\$0.00
LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR HYDRAULIC LIFT UP TAILGATE DAMPER BRACKET O/S AND REAR PANEL		\$680.00	\$200.00
TO PUTTY & SPRAY PAINTING		\$500.00	\$280.00
•		\$1,310.00	\$500.00
GRAND TOTAL	\$8,740.00	\$3,150.00	
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$2,500.00	

TOTAL FOR SPARE PARTS: \$ 7,430.00 \$ 2,650.00
TOTAL FOR LABOUR: \$ 1,310.00 \$ 500.00
TOTAL REPAIR COST: \$ 8,740.00 \$ 3,150.00

Report Ref No: CS/INC24110325/Uvh3m4

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.