LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24110326/DNP3E2

Date: 09/12/2024

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1002983256

Claimant Vehicle FREGUES OF THE PROPERTY OF THE

No: FBR6083C Insured Vehicle No: SJK7448U

Date of Loss: 10/11/2024 Nature of Claim: TP Claim No: 380553

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBR6083C

 Make & Model:
 YAMAHA X-1R, 134cc (M)
 Engine No:
 4S3001596

 Reg. Date:
 09/11/2007 (Man. Year: 2007)
 Chassis No:
 4S3001596

 Colour:
 Red
 Odometer:
 3854 km

Engine Capacity: 135 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 70/90 R17 Rear Tyre Size: 70/90 R17
Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,119.50	1,222.20	897.30	42.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	840.00	410.00	430.00	51.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
: 1,358.00 -10%Calculated Gross Total (S\$)	2,959.50	1,632.20	1,327.30	44.85
Approved Total (Overridden) (S\$)	1,30 0.0 0 1,100,00			

1,222.20 56.07 **(S\$)** 2,959.50 1,300.00 1,659.50 B 230.00 + GST 9.00/9.00% (S\$) 56.07 266.36 117.00 149.36 1,452.20 **Nett Amount (S\$)** 3,225.86 1,417.00 1,808.86 56.07

-/S 1,100.00 ASRKJ 11/12/2024

Date of Assignment: 18/11/2024

Yew Tee Automobile Tech Pte Ltd (Woodlands)

Date Inspected: 18/11/2024 Inspected At: 39 Woodlands Close #01-12, Mega@Woodlands

Singapore 737856

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(FOR MANDATE ONLY)

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 09 Dec 2024)

Parts: N/A YAMAHA X-1R 134cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBR6083C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE MIRROR LH	Not Necessary	85.00 FL	*- FL
2	1		*FRONT CLUTCH LEVER LH	Cut	28.00 FL	*28.00 FL
3	1		*FRONT SIDE FAIRING LH	Cracked	380.00 FL	*330.00 FL
4	1		*FRONT SIDE FAIRING LOGO LH	Necessary	52.00 FL	*30.00 FL
5	1		*FRONT SIDE FAIRING LAMP LH	Cut	310.00 FL	*260.00 FL
6	1		*SET FRONT FORK	Not Necessary	420.00 FL	*- FL
7	1		*FRONT HANDLE BAR	Not Necessary	270.00 FL	*- FL
8	1		*FRONT HEADLAMP	Cracked	480.00 FL	*430.00 FL
9	1	part. L=ListIte	*FRONT HEADLAMP FAIRING	Cracked	330.00 FL	*280.00 FL
1 -1 16	111011136	part. L-Listite	IIDISC.	Sub Total (S\$)	2,355.00	1,358.00
		- List Item Discount on L Items 10.00/10.00% (S\$)		235.50	135.80	
				Total Parts (S\$)	2,119.50	1,222.20
			Report was unsubmitt	red during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

230.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO ELECTRICAL WIRING SERVICES	New	30.00	30.00
2	TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE	New	150.00	0.00
3	TO COMPUTER WHEEL ALIGNMENT	New	60.00	0.00
4	TO REMOVE, REFIX, REALIGN, ADJUST AND REPLACE ALL DAMAGED PARTS	New	350.00	200.00
5	TO UNDERCOATING FOR RUST PROTECTION	New	30.00	0.00
6	TO RESPRAY PAINT OF ACCIDENT SECTION no need to paint	New	220.00	18 0.0 0
	Gross Labour Cost (S\$)		840.00	410.00
	Report was unsubmitted during this p	orint-out.		

< END OF ESTIMATES >