

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS24110327/EVP3E2

Date: 04/03/2025

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SNK199L	Insured Vehicle No :	SNA4793Y
Date of Loss:	09/10/2024	Nature of Claim:	TP
		Claim No:	DMPC2401392H/02/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNK199L		
Make & Model:	TOYOTA ALPHARD, 2.5 HYBRID STANDARD (A)	Engine No:	A25A6091346
Reg. Date:	29/04/2024 (Man. Year: 2024)	Chassis No:	JTNACAAH608002225
Colour:	Black	Odometer:	28123 km
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45Z R19	Rear Tyre Size:	245/45Z R19
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,688.30	2,249.62	33,438.68	93.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,030.00	670.00	7,360.00	91.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,718.30	2,919.62	40,798.68	93.32
Approved Total (Overridden) (S\$)		2,350.00		
(S\$)	43,718.30	2,350.00	41,368.30	94.62
+ GST 9.00/9.00% (S\$)	3,934.65	211.50	3,723.15	94.62
Nett Amount (S\$)	47,652.95	2,561.50	45,091.45	94.62

INSPECTION

Date of Assignment:	15/11/2024		
Date Inspected:	18/11/2024	Inspected At:	Bifrost Auto Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	4.0 days		

Adjuster: VERON CHEN

Manager: CHEN TSUE YEE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Mar 2025)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 HYBRID STANDARD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNK199L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Not Necessary	3,235.90 FL	*- FL
2	1		*REAR TAILGATE TAILLAMP ASSEMBLY	Not Necessary	3,329.60 FL	*- FL
3	1		*REAR TAILGATE EMBLEM	Not Necessary	68.00 FL	*- FL
4	1		*REAR TAILGATE ALPHARD EMBLEM	Not Necessary	73.70 FL	*- FL
5	1		*REAR TAILGATE BUZZER	Not Necessary	290.10 FL	*- FL
6	1		*REAR TAILGATE WIRE HARNESS	Not Necessary	317.80 FL	*- FL
7	1		*REAR TAILGATE INNER AUTO SWITCH BUTTON	Not Necessary	151.40 FL	*- FL
8	1		*REAR TAILGATE AUTO SIDE SENSOR RH	Not Necessary	1,108.30 FL	*- FL
9	1		*REAR TAILGATE AUTO SIDE SENSOR LH	Not Necessary	1,108.30 FL	*- FL
10	1		*REAR TAILGATE INNER HOLDER	Not Necessary	82.80 FL	*- FL
11	1		*REAR TAILGATE STOPPER RH	Not Necessary	27.40 FL	*- FL
12	1		*REAR TAILGATE STOPPER LH	Not Necessary	27.40 FL	*- FL
13	1		*REAR TAILGATE ELECTRICAL DAMPER RH	Not Necessary	2,448.20 FL	*- FL
14	1		*REAR TAILGATE ELECTRICAL DAMPER LH	Not Necessary	2,448.20 FL	*- FL
15	1		*REAR TAILGATE TOP LOCK	Not Necessary	550.40 FL	*- FL
16	1		*REAR TAILGATE LOWER LOCK	Not Necessary	37.20 FL	*- FL
17	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	1,104.80 FL	*- FL
18	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	481.00 FL	*- FL
19	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Not Necessary	123.90 FL	*- FL
20	1		*REAR TAILLAMP ASSEMBLY RH	Not Necessary	1,430.30 FL	*- FL
21	1		*REAR TAILLAMP ASSEMBLY LH	Not Necessary	1,430.30 FL	*- FL
22	1		*REAR TAILLAMP LOWER GARNISH RH	Repair	260.60 FL	*- FL
23	1		*REAR TAILLAMP LOWER GARNISH LH	Not Necessary	260.60 FL	*- FL
24	1		*REAR BUMPER	Broken	915.50 FL	*915.50 FL
25	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	27.50 FL	*- FL
26	1		*REAR BUMPER SIDE RETAINER FRONT RH	Not Necessary	119.90 FL	*- FL
27	1		*REAR BUMPER SIDE RETAINER FRONT LH	Not Necessary	119.90 FL	*- FL
28	1		*REAR BUMPER SIDE RETAINER REAR RH	Not Necessary	104.10 FL	*- FL
29	1		*REAR BUMPER SIDE RETAINER REAR LH	Not Necessary	104.10 FL	*- FL
30	1		*REAR BUMPER REFLECTOR RH	Not Necessary	90.80 FL	*- FL
31	1		*REAR BUMPER REFLECTOR GARNISH RH	Not Necessary	104.80 FL	*- FL
32	1		*REAR BUMPER LOWER SIDE CHROME MOULDING RH	Not Necessary	187.80 FL	*- FL
33	1		*REAR BUMPER LOWER SIDE CHROME MOULDING LH	Not Necessary	187.80 FL	*- FL
34	1		*REAR BUMPER LOWER CENTRE CHROME MOULDING	Not Necessary	243.70 FL	*- FL
35	1		*REAR BUMPER ULTRASONIC SENSOR (4PCS)	Shorted (1Pc Only)	1,571.20 FL	*392.80 FL
36	4		*REAR BUMPER ULTRASONIC SENSOR CLIPS	Necessary	51.20 FL	*51.20 FL
37	4		*REAR BUMPER ULTRASONIC SENSOR RETAINER	Not Necessary	66.80 FL	*- FL
38	1		*ELECTRICAL ANTENNA	Not Necessary	78.00 FL	*- FL
39	1		*REAR END PANEL	Not Necessary	2,050.40 FL	*- FL
40	1		*REAR END PANEL TOP GARNISH	Not Necessary	207.10 FL	*- FL
41	1		*REAR FENDER RH	Not Necessary	1,824.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*REAR FENDER QUARTER GLASS WITH MOULDING RH	Not Necessary	570.10 FL	*- FL
43	1		*REAR FENDER INNER TRIM BOARD RH	Not Necessary	1,850.40 FL	*- FL
44	1		*REAR FENDER INNER COWLING RH	Not Necessary	165.70 FL	*- FL
45	1		*REAR FENDER AIR DUCT RH	Not Necessary	138.20 FL	*- FL
46	1		*REAR AIRCON COOLING MOTOR	Not Necessary	4,025.30 FL	*- FL
47	1		*REAR FLOOR PANEL	Not Necessary	1,050.40 FL	*- FL
48	1		*REAR FLOOR PANEL TOP BOARD RH	Not Necessary	770.60 FL	*- FL
49	1		*REAR FLOOR PANEL TOP BOARD LH	Not Necessary	770.60 FL	*- FL
50	1		*REAR FLOOR PANEL TOP BOARD CENTRE	Not Necessary	551.40 FL	*- FL
51	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
52	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
53	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
54	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
55	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
56	1		*SET REAR FENDER INNER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
57	1		*SET REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
58	1		*REAR TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
59	1		*REAR END PANEL SEALANT	Not Necessary	150.00 FS	*- FS
60	1		*REAR FENDER RH SEALANT	Not Necessary	150.00 FS	*- FS
61	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Not Necessary	150.00 FS	*- FS
62	1		*REAR FENDER QUARTER GLASS RH SEALANT	Not Necessary	150.00 FS	*- FS
63	1		*REAR BUMPER LOWER DIFFUSER - (MODELLISTA KIT)	Broken	2,500.00 FS	*800.00 FS
64	1		*REAR TAILGATE REVERSE CAMERA	Not Necessary	800.00 FS	*- FS
65	1		*PAINT PROTECTION FILM (PPF)	Necessary	2,500.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	45,274.40	2,589.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	9,586.10	339.88
Total Parts (\$\$)	35,688.30	2,249.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE & REFIX PARTS	New	2,400.00	200.00
2	TO SPRAY PAINT AFFECTED AREAS	New	2,000.00	300.00
3	WIRING & BULB CHECK	New	100.00	30.00
4	TO TRANSFER REAR TAILGATE MECHANISM	New	150.00	0.00
5	TO REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS	New	150.00	0.00
6	TO REMOVE & REFIX REAR FENDER QUARTER GLASS RH	New	150.00	0.00
7	TO REMOVE & REFIX REAR BUMPER ULTRASONIC SENSORS	New	150.00	20.00
8	TO REMOVE & REFIX REAR TAILGATE REVERSE CAMERA	New	150.00	0.00
9	TO REMOVE & REFIX INTERIOR UPHOLSTRY TO FACILITATE REPAIRS	New	150.00	0.00
10	TO REMOVE & REFIX FUEL TANK TO FACILITATE REPAIRS	New	250.00	0.00
11	TO REMOVE & REFIX AIRCON COOLING MOTOR	New	150.00	0.00
12	TO APPLY ANTI RUST ON AFFECTED PARTS	New	150.00	0.00
13	TO CONDUCT WATER LEAK TEST	New	100.00	0.00
14	TO SEND DIAGNOSTIC & RESET CONTROL UNIT. PROGRAMMING & CALIBRATION	New	480.00	120.00
15	LABOUR TO APPLY PAINT PROTECTION FILM TO REPLACED PARTS	New	1,500.00	0.00
Gross Labour Cost (S\$)			8,030.00	670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >